

TECHNICAL REPORT NO. 368

TECHNICAL LIBRARY

INTERACTIVE GRAPHICS PLOTTING SYSTEM (IGPS)

BRADLEY M. LUFKIN

SEPTEMBER 1982

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED

U. S. ARMY MATERIEL SYSTEMS ANALYSIS ACTIVITY
ABERDEEN PROVING GROUND, MARYLAND

DISPOSITION

Destroy this report when no longer needed. Do not return it to the originator.

DISCLAIMER

The findings in this report are not to be construed as an official Department of the Army position unless so specified by other official documentation.

WARNING

Information and data contained in this document are based on the input available at the time of preparation. The results may be subject to change and should not be construed as representing the DARCOM position unless so specified.

TRADE NAMES

The use of trade names in this report does not constitute an official endorsement or approval of the use of such commercial hardware or software. The report may not be cited for purposes of advertisement.

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER 2. GOVT ACCESSION NO. Technical Report No. 368	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitie)	S. TYPE OF REPORT & PERIOD COVERED
INTERACTIVE GRAPHICS PLOTTING	Technical
SYSTEM (IGPS)	6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(e)	8. CONTRACT OR GRANT NUMBER(s)
Bradley M. Lufkin	
9. PERFORMING ORGANIZATION NAME AND AODRESS US Army Materiel Systems Analysis Activity Aberdeen Proving Ground, MD 21005	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS US Army Materiel Development and Readiness Command	12. REPORT DATE September 1982
5001 Eisenhower Avenue Alexandria, VA 22333	13. NUMBER OF PAGES 79
14. MONITORING AGENCY NAME & ADDRESS(if different from Controlling Office)	1S. SECURITY CLASS. (of this report) UNCLASSIFIED
16 DISTRIBUTION STATEMENT (of this Report)	ISA. OECLASSIFICATION/DOWNGRADING SCHEOULE

16. DISTRIBUTION STATEMENT (of this Report)

Approved for public release; distribution unlimited.

17. OISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)

18. SUPPLEMENTARY NOTES

The term "he" (and its derivatives) when used in this publication represent both the masculine and feminine genders; exceptions will be noted.

19. KEY WORDS (Continue on reverse side if necessary and identify by block number)

Two-Dimensional Graphics

Weibull Paper

Graph Paper

User-Definable Paper

Probability Paper

Tektronix 4051

20. ABSTRACT (Continue on reverse eigh if necessary and identify by block number)

IGPS is a computer-graphics program which produces high-quality plots of two-dimensional data; it is written in BASIC for the Tektronix 4051 desk-top computer. IGPS features: a large variety of axis systems, including probability paper for several distributions, logarithmic paper, and user-definable paper; neat tick mark and axis labeling with automatic or user-controlled decimal-point selection; several curve marker and dashed line types; legends; curve fitting; plotting of user-defined functions; data storage and retrieval on all Tektronix 4051 peripherals; and storage and retrieval of entire plots.

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

CONTENTS

																						rage
1.	INTRO	DUCTI	ON .		•			•	•	•	•		•				•	•		•	•	5
2.	USING	IGPS	S					•	•	•	•	•	•	•	• •	•	•	•		•	•	9
	2.2	User User User	кеу	Numb	er	2:	Lab	els	3.		•		•			,	•			•		10 13 13
		2.3a 2.3b 2.3c 2.3d 2.3e 2.3f 2.3f 2.3j 2.3i 2.3j	Xlo Ylo Log Use Uni Nor Log Ray	near og Pa og Pa jlog er-De form mal norm yleic bull	apen Paper Papefin Pro Pro nal	er. per. nable robal pbab Prob	e Pa bili ilit babi	iper ty y H	Papap	· · · · · · · · · · · · · · · · · · ·	r pe	· · · · · ·	•	•			•	•	•	•	•	17 17 18 20 20 25 27 29 29
	2.4	User	Кеу	Numb	er	4:	Inp	ut	ar	nd	Ou	tp	ut	•	•	•	•	•	•	•	•	32
		2.4a 2.4b 2.4c 2.4d	Out Fil	e St	ruc		 e	•	•	•	•	•	•	•	•	•	•		•	:	•	32 34 35 35
	2.5	User	Key	Numb	er	5:	Cur	ve	Fi	ts		•	•	•			•	•	•	•	•	35
	2.6	User	кеу	Numb	er	6:	405	1.	•		•	•		•	• (•	•	•	•		•	37
	2.7	User	Key	Numb	er	7:	466	2.					•	•			•	•	•		•	27
•	2.8	User	Кеу	Numb	oer	8:	sto	raç	де	an	ıd	Re	tr	ie	va.	L	•		•		•	38
	2.9	User	Кеу	Numb	er	9:	Dat	.a (Gen	er	at	io	n	•	• •	•	•	•	•	•	•	38
	2.10	User	Кеу	Numb	er	10:	M∈	nu	•	•	•	٠		•	•	•	•	•	•	•	•	41
3.	SHORT	CUTS.			•			•		•	•	•	•			•	•	•	•			43
4.	POSTS	CRIPT	г.,		•			•	•	•	•	•	•	•	•	•	•	•	•		•	47
	REFER	ENCE.										•		•			•	•	•			49
	APPEN	DIX A	7 - E	ROGE	RAM	LIS	TING		•	•	•	•	•	•	• (•	•	•	•		•	51
	DICER	TDUMT	- ON -	TOM																		77

Next page is blank

INTERACTIVE GRAPHICS PLOTTING SYSTEM (IGPS)


1. INTRODUCTION

IGPS (Interactive Graphics Plotting System) is a computer-graphics program, written in BASIC for the Tektronix 4051 desktop computer, which generates high-quality plots of two-dimensional data; the plots can be used for slide presentations or can be inserted into reports.

The program is interactive and prompts the user for all the information required to construct a plot; furthermore, the program is structured to permit rapid changes to an existing plot. Therefore, the user can keep modifying the plot he is drawing and can preview it on the screen of the Tektronix 4051 until he is satisfied with its appearance. Then, simply by depressing one key on the keyboard, the user can exactly reproduce his plot on a Tektronix 4662 x-y plotter.

Figure 1.1 is a sample plot produced in this fashion by IGPS on a 4662. The plot was drawn directly onto a piece of report paper 8-1/2 inches high by 11 inches long placed in the lower left-hand corner of the 4662. The figure number, title, and page number were then added with a conventional typewriter.

The sample, which could have been used directly to make a slide, displays some of the features of IGPS: an unusual axis system (in fact, Rayleigh Paper), neat tick mark and axis labeling, multiple curve marker types, legends, and curve fitting. Table 1-1 is a summary of the features currently available with IGPS.



WISS DISTANCE (INCHES)

Figure 1.1 Sample Plot Produced by IGPS

Tick Mark Spacing:

- uniform
- user-controlled

Tick Mark Labeling:

- uniform with automatic decimal-point selection
- user-controlled

Frame Types:

- axis
- grid
- border
- suppressed

Standard Paper Types:

- linear in x and y
- linear in x, logarithmic in y
- logarithmic in x, linear in y
- logarithmic in x, logarithmic in y
- user-definable

Probability Paper Types:

- uniform distribution
- normal distribution
- · lognormal distribution
- Rayleigh distribution
- Weibull distribution
- user-defined distribution

Input/Output Devices:

- Tektronix 4051 Internal Tape Drive
- Tektronix 4924 Auxiliary Tape Drive
- Tektronix 4907 File Manager (Disc)

Line Types:

- solid
- dashed
- dashed-dotted
- dotted

TABLE 1-1 SUMMARY OF IGPS (continued)

Curve Markers:

- crosses
- x-shaped
- squares
- triangles
- upside-down triangles

Curve Fits (Linear, Least-Squares):

- estimate slope and intercept
- estimate slope, intercept fixed
- estimate intercept, slope fixed

Plotting Devices:

- Tektronix 4051 Screen
- Tektronix 4662
- Tektronix 4662, Option 31

USING IGPS

Once IGPS has been loaded into the memory of the Tektronix 4051, it needs to be initialized. This can be done by typing in RUN followed by a carrige return. IGPS will initialize itself and will display the following menu on the screen of the 4051.




Figure 2.1 Menu for IGPS

The 10 rectangles in the menu correspond to the 10 user-definable keys located in the upper left-hand corner of the keyboard of the 4051. These 10 keys are used to control IGPS.

If, at any time during a plotting session with IGPS, the user wishes to examine the menu, he can either type in RUN followed by a carriage return or he can depress user key number 10.

Table 2-1 summarizes the action of the 10 user-definable keys.

TABLE 2-1 SUMMARY OF USER KEYS

User Key Number	Function
1	Establish limits over which plotting is done.
2	Inputs axis labels and title.
3	Defines axis system.
4	Inputs data curves from peripheral or keyboard; saves data curves on peripheral.
5	Does least-squares, linear fits on data curves.
6	Plots graph on screen of 4051.
7	Plots graph on 4662 x-y plotter.
8	Stores graph on periperal; retrieves previously saved graph from peripheral.
9	Generates x-y data from user-defined parametric functions.
10	Displays menu on the screen.

2.1 User Key Number 1: Limits.

This key is used to establish the limits between which data plotting is to take place (in other words, data outside the limits will not be plotted); the key is also used to define the distance between tick marks and between tick mark labels.

After the user depresses key number 1, IGPS will prompt him with

UNIFORM TICKS ON THE X AXIS (1=YES, 2=NO):

If the user responds with a 1, meaning that he wants uniformly spaced tick marks and labels, IGPS will prompt with

XMIN: XMAX: MAJOR TICKS: MINOR TICKS:

The user should respond to each prompt with a suitable number. The response to XMIN establishes the smallest value on the x axis and that to XMAX the largest. The response to MAJOR TICKS establishes the distance between adjacent tick mark labels and the response to MINOR TICKS the distance between adjacent tick marks. The sequence to generate the x axis of Figure 1.1, for instance, is

XMIN: 0 XMAX: 96

MAJOR TICKS: 12 MINOR TICKS: 4

In no case should XMIN ever be the same as XMAX and, for best results, MAJOR TICKS and MINOR TICKS should be multiples of the difference between XMAX and XMIN; furthermore, MAJOR TICKS should be a multiple of MINOR TICKS. Results are unpredictable if these conditions are not met. In fact, IGPS will create n tick marks, where

$$n = 1 + [(XMAX - XMIN) / MINOR TICKS],$$

and the quantity in brackets denotes "the largest integer not to exceed," and the tick marks will appear at points $\mathbf{x_i}$ such that

$$x_i = XMIN + MINOR TICKS \cdot (i-1), i=1,...,n.$$

Similarly, IGPS will create m tick mark labels, where

$$m = 1 + [(XMAX - XMIN) / MAJOR TICKS],$$

and the labels will appear at points $l_{\dot{i}}$ such that

$$l_i = XMIN + MAJOR TICKS \cdot (i-1), i=1,...,m.$$

Clearly, if MAJOR TICKS is the same as MINOR TICKS, then all tick marks will be labeled.

Consider the sequence

XMIN: 0 XMAX: 1

MAJOR TICKS: 0.25 MINOR TICKS: 0.25

This produces the following x axis




Figure 2.2 Sample Axis with Uniform Tick Marks and Labels

Note that the labels are drawn centered under the appropriate tick mark, and that all labels have the same number of digits (two) to the right of the decimal point. Note also that two digits beyond the decimal point is the ideal number in this situation, in the sense that using any fewer would have caused a loss of accuracy while using any more would have caused unnecessary trailing zeroes. IGPS calculates and uses this ideal number automatically.

If the user does not like uniformly spaced tick marks and tick mark labels with automatic decimal-point selection on the x axis, then he should respond with a 2 to the prompt

UNIFORM TICKS ON THE X AXIS (1=YES, 2=NO):

By doing so, he assumes total control over the placement and appearance of tick marks and labels; after such a response, IGPS prompts with

NUMBER OF TICK MARKS (AT LEAST 2): LOCATION OF TICK MARKS: NUMBER OF TICK MARK LABELS: LOCATION OF TICK MARK LABELS:

The meaning of these prompts is obvious.

At least two tick marks are required since the first one entered is assumed to be the minimum value along the x axis while the last one is assumed to be the maximum value. The number of tick mark labels, however, is unrestricted and may even be zero; if it is zero, the fourth prompt is not displayed since it is not needed.

The locations of tick mark labels must all be entered on one line and must be separated by a single blank or by a comma. The labels will be plotted by IGPS exactly as they were entered (in other words, IGPS will not calculate the number of places beyond the decimal point for the labels but will use as many as the user himself typed in).

For example, the sequence

NUMBER OF TICK MARKS (AT LEAST 2): 19
LOCATION OF TICK MARKS: .1 .2 .3 .4 .5 .6 .7 .8 .9
1 2 3 4 5 6 7 8 9

NUMBER OF TICK MARK LABELS: 3
LOCATION OF TICK MARK LABELS: .1 1 10

if used in conjunction with a logarithmic x axis, will produce




Figure 2.3 Sample Axis with User-Controlled Tick Marks and Labels

Once the user has supplied the specifications for the x axis, IGPS will prompt for the y axis in exactly the same way as it did for the x axis.

2.2 User Key Number 2: Labels.

This key is used to establish the axis labels and the title of the plot. If the user does not want these items, he should respond with a carriage return when prompted for them.

The x-axis label is plotted below the plotting area and is centered between the x-axis limits. The title of the plot is similarly centered but is plotted above the plotting area and is underlined twice (if the plot has no title, no underlining takes place). The y-axis label is plotted to the left of the plotting area and is centered between the y-axis limits. When plotted on the 4662 x-y plotter, the y-axis label will be written along a baseline rotated 90 degrees from the horizontal (see Figure 1.1); on the screen of the 4051, however, the individual characters are plotted on the horizontal, with the first character above the second, the second above the third, and so on (as in Chinese or Japanese) -- this is done because the character-generator of the 4051 cannot produce rotated characters. Close examination of Figure 1.1 will reveal that different character sizes are used in various parts of the plot; this feature is also only available on the 4662 because the character-generator of the 4662 can produce characters of arbitrary size, unlike the generator of the 4051.

2.3 User Key Number 3: Format.

This key is used to control the basic appearance of the graph: it determines the type of frame which will be used, the speed at which the graph will be drawn, the color of the frame

and labels and, more importantly, the type of paper which will be used.

After the user depresses user key number 3, IGPS will ask for the type of frame the user wants. There are four possible answers: zero, meaning no frame or labels are to be drawn; one, meaning draw an axis system; two, meaning draw a grid; and three, meaning draw borders.

The first option is useful when a set of curves is to be added to a graph because it avoids re-plotting most of the graph.

The second option produces axes running along the left-hand side and the bottom of the plotting area.




Figure 2.4 Sample Axis System

The third option produces a grid over the plotting area; each tick mark is indicated with a solid line.




Figure 2.5 Sample Grid

The fouth option produces axes and tick marks along the edges of the plotting area. $\,$




Figure 2.5 Sample Borders

After he selects a frame type, the user will be prompted for the color of the frame and labels. He must reply with an integer between one and eight, corresponding to the eight pens in the turret of the 4662 x-y plotter equipped with Option 31. The choice of color is ignored if plotting is either on the screen of the 4051 or on a standard 4662.

The user is then asked for a pen speed, to which he must respond with an integer between 10 and 570. The answer is interpreted in millimeters per second and is the maximum speed at which the 4662, Option 31, plotter will draw (the response is ignored on the 4051 or the standard 4662). For previewing, the user should select 570 mm/s. However, for best results, he should select 10 mm/s since the lower speed leads to much sharper definition of vectors.

The final prompt associated with user key number 3 is for the type of paper the user wants. IGPS will display

PAPER	TYPES:	X-AXIS	Y-AXIS
1.	LINEAR:	X	Y
2.	XLOG:	LOG(X)	Y
3.	YLOG:	X	LOG(Y)
4.	LOGLOG:	LOG(X)	LOG(Y)
5.	USER:	?	?
6.	UNIFORM:	X/100	Y
7.	NORMAL:	N(X/100)	Y
8.	LOGNORMAL:	N(X/100)	LOG(Y)
9.	RAYLEIGH:	SQR(-2*LOG(1-X/100))	Y
10.	WEIBULL:	LOG(-LOG(1-X/100))	LOG(Y)

PAPER TYPE:

to which the user should respond with an integer between one and 10, corresponding to his choice of paper. As indicated by the prompt, the user's choice is in fact a selection of two transformations, or functions, one function for the x axis and one for the y axis. All data, including tick mark locations (but not tick mark labels) related to the x coordinate are transformed via the x-axis function before being plotted, as are all data related to the y coordinate via the y-axis function. Since the reader may not be fimiliar with all available paper types, we will describe each one, with its associated functions, separately.

2.3a Linear Paper. This is the most commonly used type of paper and is in fact plain graph paper. The two functions associated with this paper are the identity functions and therefore have no effect.




Figure 2.6 Example of the use of Linear Paper

2.3b Xlog Paper. This paper has a logarithmic x axis and a linear y axis; therefore, all x-axis data are transformed via the function

$$F_a(x) = \ln x$$

before being plotted. Because of this transformation, there are implications for the meaning of the slope and intercept of any straight line which the user might choose to fit to his data while using xlog paper (Section 2.5, User Key Number 5). In particular, if we let a be the slope of such a line and if we let b be its intercept, and if the line appears to fit the user's data plotted on xlog paper, then an appropriate model of the user's data is:

$$y = a ln x + b$$
.

Though this may be perfectly obvious in this case, we have chosen to emphasize the point here because the situation becomes much more complex with other types of paper (transformations). In general, if we denote the two axis transformations by $F_a(x)$ and $F_b(y)$, then any straight line used with those transformations is in fact a model of the form:


$$F_b(y) = a F_a(x) + b .$$

If the user wants the model in simpler form, with only the y term appearing to the left of the equal sign, he will have to apply the inverse of $F_{\rm b}$ to both sides of the equation; this point is illustrated explicitly in the next section.

2.3c Ylog Paper. This paper has a linear x axis and a logarithmic y axis. To illustrate the use of this paper, consider the data in Table 2-2.

TABLE 2-2 VALUES	OF AIR	DENSITY	AS A	FUNCTI	ON OF	ALTITU	DE
Altitude (km)	0	1	2	3	4	5	6
Air Density (kg/m ³)	1.22	1.11	1.01	0.91	0.82	0.74	0.66
Altitude (km)	7	8	9	10	11	12	13
Air Density (kg/m ³)	0.59	0.53	0.47	0.41	0.36	0.31	0.27
Altitude (km)	14	15	16	17	18	19	20
Air Density (kg/m ³)	0.23	0.19	0.17	0.14	0.12	0.10	0.09

From physical reasoning, or for some other reason, we decide that air density is an exponential function of altitude (in other words, that the logarithm of air density is a linear function of altitude). To test this hypothesis, we plot the data on ylog paper and fit a straight line with user key number 5.



ALTITUDE (KILOMETERS)

Figure 2.7 Example of the Use of Ylog Paper

The plot confirms our hypothesis. The slope and intercept of the line calculated by IGPS are:

a =
$$-0.13$$
, and b = 0.34 .

Therefore, our model of air density (p) versus altitude (h) is:

or
$$p = -0.13 h + 0.34 ,$$

$$p = 1.40 e^{-0.13h} .$$

Note that this model does not go through the data point at zero altitude. Suppose we should want it to, in other words, suppose we should like a model of the form:

$$p = 1.22 e^{-kh}$$
.

what is the best value of k (in the least-squares sense)? Taking logarithms produces:

$$ln p = -kh + 0.20$$
.

To determine k, we depress user key number 5 and request a straightline fit with a forced intercept of

$$b = 0.20$$
.

IGPS will calculate the slope of that line as:

$$a = -0.12$$

It is clear, therefore, that the value of k we are looking for is:

$$k = 0.12$$
,

and that the best model which goes through the value of air density at zero altitude is:

$$p = 1.22 e^{-0.12h}$$
.

2.3d Loglog Paper. This paper has a logarithmic x axis and a logarithmic y axis. Therefore, straight-line fits to data plotted on this paper are models of the form:

$$ln y = a ln x + b$$
.

The user is cautioned that whenever he is using a logarithmic axis, be it horizontal or vertical, he must avoid zero or negative values along that axis, both in the data being plotted and in the choice of tick marks. This is because the logarithm of a non-positive number is undefined.

2.3e User-Definable Paper. This is one of the most powerful features of IGPS because it allows the user to define his own transformations for the axes and therefore provides an unlimited supply of paper types. If you want to use this feature, you must define your transformations before you depress user key number 3 and you must then select user-definable paper.

To define your transformations, you must replace lines 4590 and 4600 in the program with your own functions. The transformation for the x axis must appear on line 4590 and must be of the form

4590 DEF FNA(X)=

where you supply the information to the right of the equal sign. Line 4600 is for the y axis and must be of a similar form

4600 DEF FNB(Y) =

To illustrate the power of this feature, consider the data appearing in Table 2.3.

TABLE 2-3 SAMPLE DATA

x	3.00	2.70	2.30	1.80	1.60	1.27	1.10	
У	.225	.241	.267	.304	.321	.351	.365	

Plotting the data on ordinary, linear, graph paper reveals nothing unusual about them.




Figure 2.8 Sample Data Plotted on Linear Paper

Incidentally, the source of the data and the units associated with them do not concern us here. What does concern us is that a model of the form

$$y = \frac{k}{\sqrt{x}}$$

has been suggested for the data. To test this model, we type in

4590 DEF FNA(X)=-1/SQR(X)

4600 DEF FNB(Y)=Y

we select user-definable paper and we ask for a curve fit with a forced intercept of b=0.




Figure 2.9 Sample Data Plotted on User-Defined Paper

IGPS calculates the slope of the line as a = -0.40. This means that one possible model of the data is:

$$y = \frac{0.40}{\sqrt{x}}$$

Note that the x axis on user-definable paper starts at 1, whereas the x axis on ordinary paper starts at zero. This difference is necessary because the transformation of zero on user-definable paper would lead to an undefined number (in other words,

$$\frac{-1}{\sqrt{0}} = -\infty$$
). Note also that we defined the x-axis trans-

formation as

$$F_a(x) = -\frac{1}{\sqrt{x}}$$
, rather than as

$$F_a(x) = \frac{1}{\sqrt{x}} .$$

The minus sign is required to make the transformed value of the minimum along the x axis smaller than the transformed value of the maximum (in other words, if the minus sign had not been included, we would have had $F_a(1) > F_a(4)$, which is not allowed

on the Tektronix). The minus sign has to be taken into account when interpreting the results of the curve fitting (which was done in constructing the final model above).

The final point to make about this example is that the value of the free parameter in our model could have been read directly off the graph at the point where the fitted line intersects the vertical line x=1. One way to see this is to note that, in our model, y=k when x=1.

What this example has illustrated is that user-definable paper, in conjunction with curve-fitting, can be used to test the adequacy of a large class of models in representing given data (though no mention of this has yet been made, it will be shown in Section 2.5 that IGPS, when curve-fitting, generates a quantitative esitmate of the goodness-of-fit of the model; this estimate is known as R^2). As another example, consider the data in Table 2-4.

TABLE 2-4 MORE SAMPLE DATA

х	1	2	3	4	
У	1.01	2.28	3.92	6.13	

One proposed model for these data is:

$$y = \frac{x}{1.1 - kx}$$

By inverting both sides of the equation and multiplying by -1, this model can be transformed into:

$$-\frac{1}{y} = -\frac{1.1}{x} + k.$$

Therefore, we can check the adequacy of the original model by typing

4590 DEF FNA(X)=
$$-1/X$$

4600 DEF FNB(Y)= $-1/Y$

and then selecting user-defined paper and doing a curve fit with a forced slope of a = 1.1.




Figure 2.10 Another Example of User-Defined Paper

The plot shows that the model is a good one and as IGPS calculates the intercept of the line as b=0.11, we know the value of the free parameter k. Therefore our model becomes:

$$y = \frac{x}{1.1 - 0.11x}$$

This example illustrates that a particular model may need to be manipulated before it can be used to define a paper type. In general, to define a paper type, a model will have to be put into the form:

$$F_b(y) = a F_a(x) + b$$
,

where F_a and F_b are functions of x and y and where a and b are functions of the free parameters of the original model.

The paper types described so far have been suitable for sets of two-dimensional, x-versus-y, data. We now describe several types of paper suitable for testing whether a set of data is from a particular probability distribution.

2.3f Uniform Probability Paper. Let us imagine that we have a sample of n points, d_i , $i=1,\ldots,n$, from a uniform distribution on the interval (A,B). Suppose further that the cumulative fraction of the data associated with the i^{th} point is q_i , $i=1,\ldots,n$. The q_i 's can be determined in two steps: (1) sort the d_i 's into increasing order and (2) calculate q_i as:

$$q_i = \frac{i}{1+n}$$
, $i=1,\ldots,n$.

Since the $\ensuremath{\mathtt{d}}_i\ensuremath{^{'}}\ensuremath{\mathtt{S}}$ are uniformly distributed, it must be the case that

$$q_i = F(d_i), i=1,...,n$$
,

where F is the cumulative distribution function (c.d.f.) of the uniform distribution on (A,B):

$$q = F(x) = \begin{cases} 0, & x < A, \\ x - A, & A \le x \le B, \text{ and} \\ 1, & x > B. \end{cases}$$

It follows, therefore, that

$$d_i = F^{-1}(q_i)$$
, $i=1,...,n$,

where F^{-1} represents the inverse of F (the existence of F^{-1} can be guaranteed by restricting the domain of F to the interval A \leq x \leq B). In other words,

$$d_i = (B-A) q_i + A, i=1,...,n$$

so that if we plot the d_i 's against the q_i 's, we should be able to fit a straight line to the plotted points; what is more, if the slope of the line is a and its intercept is b, we can calculate the parameters of the distribution from a = B - A and b = A; these two equations in fact imply A = b and B = a + b.

Consider the data in Table 2-5.

TABLE 2-5 UNIFORM NUMBERS

5.39	5.87	6.41	5.00
6.76	6.01	6.62	5.64
5.41	6.28	6.87	5.65
5.81	6.50	5.17	6.41
6.83	6.74	5.22	5.16

To check the uniformity of the data, we sort them in increasing order, generate the associated cumulative fractions, and plot them after asking for a curve fit (IGPS will, if requested, do the sorting and the generating of cumulative fractions; note that the fractions are expressed as percentages, however). The plot provides convincing evidence of the uniformity of the numbers; furthermore, the curve fit produces a slope a = 2.24 and an intercept b = 4.87. We conclude that the numbers are from a uniform distribution on (4.87, 7.11).




Figure 2.11 Example of the Use of Uniform Probability Paper

2.3g Normal Probability Paper. This paper can be used to check if a given sample of data is from a normal, or gaussian, distribution.

Imagine that we have a sample of n points d_i , i=1,...,n, from a normal distribution with unknown parameters m and s. We can transform the di's to standard form by setting

$$z_i = \frac{d_i - m}{s}$$
, $i=1,\ldots,n$.

Furthermore, since the di's are normally distributed, then the zi's are distributed according to the standard normal distribution, and it must therefore be the case that

$$q_{i} = F(z_{i}), i=1,...,n$$

where the $q_{\dot{\mathbf{1}}}$'s are the cumulative fractions of the data and F is the c.d.f. of the standard normal distribution:

$$F(x) = \frac{1}{\sqrt{2\pi}} \int_{-\infty}^{x} e^{-1/2 t^2} dt$$
.

It follows that
$$z_i = F^{-1}(q_i), i=1,...,n$$
,

and from the definition of z; we have

$$\frac{d_i - m}{d_i} = F^{-1}(q_i), i=1,...,n$$

or

$$d_i = s F^{-1} (q_i) + m, i=1,...,n$$
.

Therefore, if we plot d; against $F^{-1}(q_i)$, $i=1,\ldots,n$, the result will approximate a straight line whose slope and intercept can be used directly to estimate m and s. Consider the data in Table 2-6.

TABLE 2-6 NORMALLY DISTRIBUTED DATA (FREQUENCY)


Frequency	.12	.22	.29	.18	.15	.02
Value	3.0	3.5	4.0	4.5	5.0	5.5

The same data, in cumulative form, appears in Table 2-7.

TABLE 2-7 NORMALLY DISTRIBUTED DATA (CUMULATIVE)

Cumulative Frequency (%)	12	34	63	81	96	98
Value	3.0	3.5	4.0	4.5	5.0	5.5

We enter the data in Table 2-7 into IGPS after selecting normal paper and we do a curve fit.



CUMULATIVE FREQUENCY (%)

Figure 2.12 Example of the Use of Normal Probability Paper

Estimates of the mean and standard deviation provided by the curve fitting are m=3.82 and s=0.75. These two quantities can also be estimated from the graph: the mean is the point at which the line intersects the $50^{\,\mathrm{th}}$ percentile while the standard deviation is the difference between this value and the value

corresponding to a cumulative fraction of 0.8413. These assertions can be verified as follows: our model is of the form

$$d = sF^{-1}(q) + m,$$

and therefore d=m where $F^{-1}(q)=0$ and $F^{-1}(q)=0$ when q=0.50. To find s, note that s=d-m when $F^{-1}(q)=1$ and this is true when q=0.8413. Another way to see this is to note that the mean and median of the standard normal distribution are equal while one standard deviation about the mean spans 68.26 percent of the distribution (and 50 percent plus one-half of 68.26 percent equals 84.13 percent).

Note that the x-axis tick mark labels on the graph avoid the values zero and 100. This should always be done when using normal paper because $F^{-1}(0) = -\infty$ and $F^{-1}(1) = +\infty$.

Finally, a remark about F^{-1} itself: since F^{-1} cannot be expressed in closed form (that is to say in terms of sums and products of functions available on the Tektronix 4051), IGPS uses an approximation of F^{-1} due to Hastings (reference 1, page 192).

The approximation is:

$$F^{-1}(q) = \begin{cases} G(1-q), & q > .5, \\ -G(q), & q \leq .5, \end{cases}$$
 and

where

$$G(q) = z - \frac{h(z)}{s(z)},$$

$$z = \ln \frac{1}{q^2},$$

$$h(z) = 2.515517 + 0.802853 z + 0.010328 z^2$$
, and
$$s(z) = 1 + 1.432788 z + 0.189269 z^2 + 0.001308 z^3.$$

It is claimed that the error made in using the approximation is never greater than 0.0004 standard deviations.

- 2.3h Lognormal Probability Paper. Lognormal paper is similar to normal paper in all respects save one: the y axis of lognormal paper is logrithmic whereas the y axis of normal paper is linear. Therefore, lognormal paper can be used to test whether a sample of data is from a lognormal distribution, that is to say, that the logarithm of the sample is normally distributed.
- 2.3i Rayleigh Probability Paper. The Rayleigh distribution has c.d.f.

$$q = F(d) = 1 - e - \frac{1}{2} \left(\frac{d}{s}\right)^2$$
.

This can be readily transformed into


$$d = s \sqrt{-2 \ln (1 - q)}$$
.

Therefore, given a sample of n points d_i , $i=1,\ldots,n$, with cumulative fractions q_i , $i=1,\ldots,n$ we can test whether the sample is from a Rayleigh distribution by plotting d_i against $\sqrt{-2 \ln (1-q_i)}$, $i=1,\ldots,n$. Furthermore, we can estimate s by fitting a line with intercept b = 0 and slope a to the transformed data and setting s = a. The data in Table 2-8 will illustrate the procedure.

TABLE 2-8 NUMBERS FROM A RAYLEIGH DISTRIBUTION

320	470	16	619
356	547	264	204
429	703	265	305
501	128	468	662
608	143	121	524

We input the data to IGPS, ask IGPS to sort it and generate the cumulative fractions, ask IGPS for a curve fit with a forced intercept of b=0, and plot the results on Rayleigh paper.



CUMULATIVE FREQUENCY (%)

Figure 2.13 Example of the use of Raleigh Probability Paper

One estimate of the parameter s is provided by the curve fit as s=314. Another is provided directly from the graph at the point where the line intersects the 39^{th} percentile. This is the case because our model is:

$$d = s \sqrt{-2 \ln(1-q)},$$

and therefore d = s when $\sqrt{-2 \ln (1-q)}$ = 1, which is the case when q = 39%.

Note that the value 100 is not used as an x-axis tick mark label; this is because when q = 1, $\sqrt{-2}$ ln (1-q) = + ∞ .

2.3j Weibull Probability Paper. The Weibull distribution has c.d.f.

$$q = F(d) = 1 - e^{-kd}, d > 0, k > 0.$$

This can be transformed, by taking logarithms twice, into

$$\ln d = \frac{1}{c} \ln [-\ln (1 - q)] - \frac{1}{c} \ln k$$
.

Weibull paper is ruled according to the function

$$F_a(x) = \ln \left[-\ln \left(1 - x\right)\right]$$

along the x axis and according to the function

$$F_{b}(y) = ln y$$

along the y axis. Therefore, given a set of data d_i , $i=1,\ldots,n$, from a Weibull distribution with parameters c and k, with associated cumulative fractions q_i , $i=1,\ldots,n$, then, if we plot d_i against q_i , $i=1,\ldots,n$, on Weibull paper, the result should approximate a straight line. Furthermore, if the slope of the line is a and its intercept is b, then estimates of c and k are given by

$$c = \frac{1}{a}$$
, and

Note that, because of the definition of F_a , values of zero and 100 should be avoided on the x-axis (in fact, $F_a(0) = -\infty$ and $F_a(1) = +\infty$); similarly, non-positive values should not be used along the y axis.

Before leaving this section, we should point out that the user can define his own probability paper by using the ideas developed in Section 2.3e. For instance, suppose the user is interested in constructing paper for the exponential distribution. Now the exponential distribution has c.d.f.

$$g = F(d) = 1 - e^{-cd}, c > 0.$$

By rearranging and taking logarithms, this can be converted to

$$d = -\frac{1}{c} \quad \ln (1 - q) .$$

Therefore, to construct exponential paper, the user would type in:

4590 DEF
$$FNA(X) = -LOG(1-X/100)$$

$$4600$$
 DEF FNB(Y)=Y

and would then select user-definable paper. Note that the argument of the function FNA is divided by 100; this is done to allow the x-axis tick marks and labels to be expressed as percentages.

We leave to the reader the problem of determining what kind of curve fit to use with exponential paper and how to estimate the parameter c from the results of the curve fit.

The overall strategy for creating distribution paper, however, is clear: the c.d.f. of the distribution of interest is manipulated into the form

$$F_b(d) = a F_a(q) + b$$
,

where F_a and F_b are functions of the cumulative frequency of the data and of the data itself and a and b are functions of the free parameters of the distribution.

2.4 User Key Number 4: Input and Output.

This key is used either to input data curves into IGPS or to save previously entered curves from IGPS onto a Tektronix peripheral.

2.4a Input. After the user chooses to input data into IGPS, he will be prompted with

DATA TYPE
$$(1 = Y \text{ ONLY, } 2 = X \& Y)$$
:

A response of 1 indicates that the user is only going to input y-coordinate data whereas a response of 2 indicates that he is going to input both x-axis and y-axis data. A response of 1 is also a request to IGPS to do two things: (1) sort the y-axis data in increasing order and (2) generate x-axis data as:

$$x_{i,j} = 100$$
 , $j = 1,...,m_i$, $i = 1,...,n$, $1 + m_i$

where n is the number of curves in the data set and m_i is the number of points in the i^{th} curve. This feature is useful with probability paper; see sections 2.3f through 2.3j.

The user is then prompted for the device he wants to read the data curves from. There are four possible responses: one, meaning the Tektronix 4907 File Mangager, a disc system; two, the Tektronix 4924 Auxiliary Tape Drive; three, the Tektronix 4051 Internal Tape Drive; and four, meaning the user wants to input data into IGPS by typing it on the keyboard of the 4051.

The user is then prompted for the number of curves he wants to input and for the number of points in the curve having the largest number of points (in other words, for the number \mathtt{m}_0 where $\mathtt{m}_0=\max \;[\; \mathtt{m}_i,\; i=1,\ldots,n\;]$, where n is the number of curves being input and \mathtt{m}_i is the number of points in the i^{th} curve).

If the user selected the 4907 as the device to use, he is then prompted for the names of the files on which his data reside; if he selected either the 4924 or the internal tape drive, he is then prompted for the numbers of the files; and if he selected the keyboard, he is prompted for the number of points and for the values of the data points in each curve (furthermore, if the user selected y-only data, he is only prompted for the y-axis values, whereas, if he selected x & y data, he is prompted for both x-axis and y-axis values).

When IGPS has read in all the data, it asks for the type of curve marker to be used with each curve. These are nine different curve markers available:




Figure 2.14 Available Curve Markers

Interesting effects can be achieved by plotting the same curve more than once, with a different curve marker each time.

IGPS next prompts for the legend the user wants for each curve; if the user does not want a legend, he should respond with a carriage return. The legend for a particular curve is plotted slightly to the right of the last data point in the curve. This feature was used to create the symbols one through nine in the plot above.

Finally, IGPS prompts for the color the user wants for each curve. Allowable responses are integers between one and eight; these refer to the eight pens in the turret of the Tektronix 4662 x-y plotter equipped with Option 31. The responses are ignored if plotting is either on the screen of the 4051 or on the standard 4662.

If the user selected y-only data, there may now be a slight pause as IGPS sorts the y-axis data and generates the x-axis data. The y-axis data are sorted in place and the original order of the data is therefore lost.

2.4b Output. After the user chooses to output data from IGPS onto a peripheral device, he is prompted for the type of data he wants to save, either y-only or x & y. In the first case, only the y-axis values will be output, whereas in the second, both x-axis and y-axis data are transmitted.

IGPS then prompts for the device the user wishes to output the data to. Possible responses are: one, the 4907; two the 4924; and three, the 4051 Internal Tape. If the user chooses the 4907, IGPS will then ask for the file names on which to write the data; if he chooses the 4924 or the internal tape, it asks for the file numbers.

When writing to the 4907, IGPS will create files of the appropriate size for the data to be written; for tape devices, however, the user must use the MARK command to create the files on his tape before saving data. The tape files must be s bytes long, where

$$s = \begin{cases} 19 + 19 \cdot m & \text{for y-only data} \\ 19 + 37 \cdot m & \text{for x & y data} \end{cases}$$

and m is the number of points in the curve to be written to the file. In practice, the default minimum file size of 768 bytes is adequate for most curves.

If the user attempts to output data without ever having input data during the session, an error message is printed.

2.4c File Structure. Data files to be read by IGPS or written by IGPS are in ASCII format. The structure of an IGPS-compatible file is as follows: (1) the first record in the file contains the number of points in the file; (2) each subsequent record consists of either a single number or of a data pair, depending on whether the file is a y-only or an x & y data file.

 $2.4 \,\mathrm{d}$ Address Number of the 4924. IGPS assumes that the 4924 Auxiliary Tape Drive is at address 2 of the General Purpose Interface Bus (GPIB). If the user's 4924 is at a different address, he will need to change IGPS. An example will illustrate the required change: if the address wanted is, say, 4 then the user should type in

$$9350 DO = 4$$
.

This must be done before initialization of IGPS.

2.5 User Key Number 5: Curve Fits.

This key is used to do least-squares, linear fits to the user's data. There are several types of fit available: (1) unconstrained, where IGPS calculates both the slope and intercept of the line which best fits the user's data; (2) fixed-slope, where IGPS calculates the intercept of the best line with user-defined slope; and (3) fixed-intercept, where IGPS calculates the slope of the best line with user-defined intercept. A fourth option allows the user to check the goodness of fit of any line he wishes. In all cases, IGPS operates not on the data the user inputs into IGPS but on the data after it has been transformed via the two functions which define the type of paper the user has asked for (see section `.3). For instance, if the user asked for xlog paper, the curve fit is to the logarithm of the x-axis data values.

The following equations are used by IGPS for the different curve fits. Assume we are given a set of transformed data (x_i, y_i) , $i = 1, \ldots, n$, where n is the number of points in the set, to which we wish to fit a line of the form y = ax + b. The sum of the squares of the vertical deviations between the line and the data points is

$$D = \sum_{i=1}^{n} [y_i - (ax_i + b)]^2$$
.

In order to do an unconstrained curve fit, in other words, to calculate both a and b, we differentiate D with respect to a and b and set the results to zero:

$$\frac{dD}{da} = \sum_{i=1}^{n} (2) \left[y_i - (ax_i + b) \right] (-x_i) = 0$$

$$\frac{dD}{db} = \sum_{i=1}^{n} (2) \left[y_i - (ax_i + b) \right] (-1) = 0$$

A little algebra reduces these equations to:

$$a = \frac{\sum_{i=1}^{n} x_{i}y_{i} - \sum_{i=1}^{n} x_{i} \sum_{i=1}^{n} y_{i}}{\sum_{i=1}^{n} x_{i}^{2} - \left(\sum_{i=1}^{n} x_{i}\right)^{2}}, \text{ and}$$

$$b = \frac{1}{n} \left(\sum_{i=1}^{n} y_{i} - a\sum_{i=1}^{n} x_{i}\right).$$

In order to do a fixed-slope curve fit, in other words, in order to calculate b given a, we differentiate D with respect to b and set the result to zero, which yields the equation for b given above. In order to do a fixed-intercept fit, in other words, in order to calculate a given b, we differentiate D with respect to a and set the result to zero, which produces:

$$a = \frac{\sum_{i=1}^{n} x_{i}y_{i} - b \sum_{i=1}^{n} x_{i}}{\sum_{i=1}^{n} x_{i}^{2}}.$$

In all cases, IGPS calculates and displays a measure of the goodness of fit of the particular line through the data points. The measure is known as \mathbb{R}^2 and is defined as:

$$R^{2} = 100 \cdot \left\{ 1 - \frac{D}{\sum_{i=1}^{n} (y_{i} - \overline{y})^{2}} \right\},$$

where D is as before and \overline{y} is the average of y_i , $i=1,\ldots,n$:

$$\overline{y} = \frac{1}{n} \sum_{i=1}^{n} y_i$$
.

From the definition of \mathbb{R}^2 , it is apparent that the closer \mathbb{R}^2 is to 100, the better the fit.

The prompts associated with user key number 5 are straightforward and require no discussion.

2.6 User Key Number 6: 4051.

This key is used to plot the current graph on the screen of the Tektronix 4051. If the graph is not complete, in other words, if some item of information needed to construct the graph has not been supplied to IGPS, the program will prompt the user for the missing item.

This key is particularly useful in previewing a plot: the user can look at the plot on the screen by depressing this key; if he doesn't like what he sees, he can use the other keys (or the shortcuts described in Section 3) to alter the parameters of the plot; finally, he can depress key number 6 again to quickly see the results of any changes he may have made. Of course, if the user takes no action between depressions of the key, then the plot will be re-drawn on the screen without changes.

Once the user is satisfied with the plot, he can get a copy of it on the Tektronix 4662 x-y plotter by depressing user key number 7.

2.7 User Key Number 7: 4662.

This key is used to obtain a hard copy of the current graph on Tektronix 4662 x-y plotter. Before using this key, the user should prepare the 4662 for plotting by placing a piece of paper in the lower left-hand corner of the plotting area of the 4662. If the piece of paper is l1 inches long and eight and one-half inches high, and if the hardware limits of the 4662 are left at their default values, the plot produced by IGPS will be centered on the piece of paper (see Figure 1.1). To produce plots of different sizes, the user can either change the hardware limits of the 4662 or he can modifiy the definition of the viewport in IGPS (see the listing of IGPS in Appendix A at lines 6620 through 6660).

IGPS assumes that the 4662 plotter is at address 1 of the GPIB. If the user's 4662 is at a different address, he will need to change line 28 of the program to read

· 28 D=

where the new address goes to the right of the equal sign.

2.8 User Key Number 8: Storage and Retrieval.

This key is used to store onto a peripheral or retrieve from a peripheral all the information required to construct a particular plot. This feature is useful in that it allows a complex plot to be saved during one session with IGPS and then quickly reconstructed at a later session without the user having to re-input all the parameters which make up the plot; instead, the entire plot can be recreated by just depressing this one key and responding to a few prompts.

After the user depresses key number 8, IGPS will prompt him for the type of operation to carry out (either storage or retrieval). The user is then prompted for the device he wishes to use. There are three possible responses: one, meaning the 4907 file manager; two, meaning the 4924 Tape Drive; and three, meaning the internal drive. If the user selected the 4907, he is then prompted for the name of the file to use; if he selected the 4924 or the interval tape drive, he is prompted for the number of the file.

If the user attempts to store an incomplete plot, an error message is printed and no further action is taken.

When storing a plot on the 4907, IGPS will create a binary file of the appropriate size for the data to be written; for tape devices, the user must use the MARK command to create the file on his tape. The tape file must be S bytes long, where S is approximately given by the expression

$$s = 1000 + 16 \cdot n \cdot m_{O}$$

where n is the number of data curves in the plot and m_0 is the number of points in the curve having the greatest number of points; for instance, storing Figure 1.1 requires approximately 2000 bytes.

The remarks in 2.4d about the address of the 4924 apply here as well.

2.9 User Key Number 9: Data Generation.

This key can be used to generate x axis and y axis data from user-defined parametric functions rather than inputting them from a peripheral or the keyboard.

After the user depresses this key, IGPS will prompt with:

DATA TYPE (1=Y ONLY, 2=X&Y): NUMBER OF CURVES: NUMBER OF POINTS PER CURVE (AT LEAST 2): MIN AND MAX OF PARAMETRIC VARIABLE:

The meaning of the DATA TYPE prompt is as before: a response of l is a request to IGPS to sort the y axis data in increasing order and to generate x axis data as cumulative fractions.

IGPS will, after the user responds to the prompts, create the data as

$$X_{i,j} = F_{x} [t_{o} + S \cdot (j-1)]$$
 and $Y_{i,j} = F_{y} [t_{o} + S \cdot (j-1)]$,

where $j = 1, ..., m_O$, i=1, ..., n, n and m_O are the responses to the second and third prompts,

$$S = \frac{t_1 - t_0}{m_0 - 1},$$

 $t_{\rm O}$ and $t_{\rm I}$ are the minimum and maximum of the parametric variable, and $F_{\rm X}$ and $F_{\rm Y}$ are the user-definable functions. These two functions must be defined by the user before he depresses user key number 9; he must do so by replacing lines 3420 and 3430 in the program with his own functions: line 3240 is for $F_{\rm X}$ and must be of the form

3420 DEF
$$FNX(T) =$$

while line 3430 is for $\mathbf{F}_{\mathbf{V}}$ and must be of the form

$$3430 \text{ DEF FNY(T)} =$$

By default, the definitions are

3420 DEF FNX(T)=RO(I)*SIN(T)

3430 DEF FNY(T)=RO(I)*SIN(T)*COS(T)

where RO is an array with five entries such that

$$RO_i = i, i=1,...,5.$$

Therefore, if the user does not alter the definitions, and if he uses the following sequence

DATA TYPE (1=Y ONLY, 2=X&Y): 2 NUMBER OF CURVES: 5 NUMBER OF POINTS PER CURVE: 21 MIN AND MAX OF INDEPENDENT VARIABLE: 0, 6.28

then, with appropriate choices of limits, labels, curve types and so on, he should be able to reproduce Figure 2.15.




Figure 2.15 Sample Plot Using Parametric Functions

2.10 User Key Number 10: Menu.

Whenever this key is depressed, IGPS will plot the menu on the screen of the 4051; see Figure 2.1.

Next page is blank

3. SHORTCUTS

Suppose you are previewing a plot on the screen of the Tektronix 4051 and you decide to change the type of curve marker being used with one of the curves. One way to do this is to depress user key number 4 and to go through the input procedure; this, however, is clumsy and can be avoided since the variable controlling the type of curve marker is directly available to the user: it is in fact the array LO, with as many entries as there are curves, and with the ith entry of LO being an integer between one and nine (see Figure 2.14) corresponding to the type of curve marker to be used with the ith curve. Therefore, to change the type of curve marker for a given curve, the user need only change the entry in LO corresponding to that curve. For instance, to draw the third curve as a solid line, the user should type in LO(3)=4.

The same procedure can be used with any of the features of the plot being previewed. To find out the name of the variable which controls the feature of the plot which you want to change, consult Table 3-4.

TABLE 3-1 DICTIONARY OF VARIABLES

		
Name	Туре	Description
Nl	Simple	Number of entries in Xl
X1(N1)	Array	Locations of x axis tick marks
N3	Simple	Number of entries in Yl
Y1(N3)	Array	Locations of y axis tick marks
N2	Simple	Number of entries in A\$
Așa	String	X axis tick mark labels
N4	Simple	Number of entries in B\$
_B \$a	String	Y axis tick mark labels
X\$	String	X axis label
Y\$	String	Y axis label
Z \$	String	Title of plot
Z \$	String	Title of plot

a see remarks

TABLE 3-1 DICTIONARY OF VARIABLES (CONTINUED)

Name	Type	Description
AO	Simple	Frame type:
		0 - None 1 - Axes 2 - Grid 3 - Border
FO	Simple	Color for frame and labels (must be integer between one and eight)
S0	Simple	Pen speed (must be number between 10 and 570)
pa	Simple	Paper type:
		<pre>1 - linear 2 - Xlog 3 - Ylog 4 - Loglog 5 - User-defined 6 - Uniform probability 7 - Normal probability 8 - Lognormal probability 9 - Rayleigh probability 10 - Weibull probability</pre>
N	Simple	Number of curves
МО	Simple	Number of points in the curve with the greatest number
M(N)	Array	M(I) contains the number of points in the i th curve
X(N,MO)a	Array	X(I,J) contains the j th data point in the i th curve
Y(N,MO)a	Array	Y(I,J) contains the j th data point in the i th curve

a see remarks

TABLE 3-1 DICTIONARY OF VARIABLES (CONTINUED)

Name	Type	Description
LO(N)	Array	LO(I) contains the curve type for the i th curve:
		<pre>1 - Dashed line 2 - Dashed-dotted line 3 - Dotted line 4 - Solid line 5 - Crosses 6 - X-shaped markers 7 - Squares 8 - Triangles 9 - Upside-down triangles</pre>
FŞa	String	Legends for the N curves
CO(N)	Array	CO(I) contains the color of the i th curve and legend (must be integer between one and eight)
	0.1	
С	Simple .	Curve fit:
		0 - No ≠0 - Yes
A(N)a	Array	A(I) contains the slope of the line fit to the i th set of data
B(N)a	Array	B(I) contains the intercept of the line fit to the i th set of data
R(N)a	Array	R(I) contains the R ² - value associated with the fit to the i th set of data

a see remarks

REMARKS:

1. The strings A\$ and B\$ contain the tick mark labels in compact form, which is to say, A\$ consists of N2 labels juxtaposed and separated by pound signs (#). Therefore, the tick mark labels associated with Figure 2.2 could have been created by typing in

N2=5

A\$="0.00#0.25#0.05#0.75#1.00#"

- 2. Changes to the variable P must be followed by the statement RUN 4410.
- 3. Unused entries of the arrays X and Y are zero-filled.
- 4. F\$ contains the N legends in compact form (see remark 1 for a definition of compact). The legends in Figure 1.1 could have been created by the statement

F\$="MARK I# MARK II#"

5. The contents of the arrays A, B, and R are only meaningful if a curve-fit has been performed. Otherwise, they are zero-filled.

4. POSTSCRIPT

The author has attempted to make IGPS as useful and versatile as possible and he welcomes recommendations for improving it.

REFERENCE

1. Hastings, C. Approximations for Digital Computers, Princeton University Press, Princeton, NJ, 1955.

APPENDIX A PROGRAM LISTING

APPENDIX A PROGRAM LISTING

SET UP USER-DEFINABLE KEYS AND PROGRAM INITIALIZATION (NOTE: 4662 ASSUMED AT ADDRESS 1 OF GPIB; SEE LINE 28)

1 GOSUB 9330
2 GO TO 3640
4 GO TO 100
8 GO TO 1310
12 GO TO 4150
16 GO TO 1410
20 GO TO 5560
24 D=32
25 GO TO 6390
28 D=1
29 GO TO 6390
32 GO TO 4920
36 GO TO 3370

USER KEY 1: SET UP AXIS LIMITS AND LABELS

- 100 PAGE
- 110 DELETE X1,Y1

40 GO TO 3640

- 120 A\$=""
- 130 PRINT "UNIFORM TICKS ON THE X-AXIS (1=YES, 2=NO):";
- 140 INPUT L

SELECT TYPE OF X-AXIS LABELING

150 GO TO L OF 160,400

1.AUTOMATIC X AXIS

160 REM 170 M1=0PRINT "XMIN:"; 180 190 GOSUB 1010 200 D1=VAL(W\$) 210 PRINT "XMAX:"; 220 GOSUB 1010 230 D2=VAL(W\$)PRINT "MAJOR TICKS:"; 240 250 GOSUB 1010 260 D4=VAL(W\$)PRINT "MINOR TICKS:"; 270 280 INPUT D3 290 N1=1+INT((D2-D1)/D3)DIM X1(N1) 300 310 FOR I=1 TO N1X1(I) = D1 + (I-1) * D3320

```
330
     NEXT I
      N2=1+INT((D2-D1)/D4)
340
350
      FOR I=D1 TO D2 STEP D4
360
        GOSUB 1060
        A$=A$&W$
370
380
      NEXT I
390
      GO TO 540
             2. USER-CONTROLLED X AXIS
400 REM
410
     PRINT "NUMBER OF TICK MARKS (AT LEAST 2):";
420
      INPUT N1
430
      DIM X1(N1)
440
      PRINT "LOCATION OF TICK MARKS:";
450
      INPUT X1
      PRINT "NUMBER OF TICK MARK LABELS:";
460
      INPUT N2
470
480
      IF N2=0 THEN 530
490
        PRINT "LOCATION OF TICK MARK LABELS:";
500
        INPUT W$
510
        GOSUB 1230
520
        A$=W$
530
      REM
540 REM
550 B$=""
560 PRINT "UNIFORM TICKS ON THE Y-AXIS (1=YES, 2=NO):";
570 INPUT L
             SELECT TYPE OF Y-AXIS LABELING
580 GO TO L OF 590,830
                 1. AUTOMATIC Y AXIS
590 REM
600
      M1=0
      PRINT "YMIN:";
610
      GOSUB 1010
620
630
      D1 = VAL(W$)
640
      PRINT "YMAX:";
650
      GOSUB 1010
660
      D2=VAL(W$)
      PRINT "MAJOR TICKS:";
670
680
      GOSUB 1010
690
      D4 = VAL(W$)
700
      PRINT "MINOR TICKS:";
      INPUT D3
710
720
      N3=1+INT((D2-D1)/D3)
730
      DIM Y1(N3)
740
      FOR I=1 TO N3
750
        Y1(I)=D1+(I-1)*D3
760
      NEXT I
770
      N4=1+INT((D2-D1)/D4)
780
      FOR I=D1 TO D2 STEP D4
```

```
790
         GOSUB 1060
 800
         B$=B$&W$
 810
       NEXT I
 820
       GO TO 970
                   2. USER-CONTROLLED Y AXIS
 830 REM
       PRINT "NUMBER OF TICK MARKS (AT LEAST 21:";
 840
       INPUT N3
 850
 860
       DIM Y1(N3)
       PRINT "LOCATION OF TICK MARKS:";
 870
 880
       INPUT Yl
     PRINT "NUMBER OF TICK MARK LABELS:";
 890
 900
       INPUT N4
 910
       IF N4=0 THEN 960
 920
         PRINT "LOCATION OF TICK MARK LABELS:";
 930
         INPUT W$
         GOSUB 1230
 940
 950
         B\$=W\$
 960
     REM
 970 REM
 980 \text{ K}(1)=1
 990 PAGE
1000 RETURN
 ROUTINE TO CALCULATE THE NUMBER OF DIGITS TO THE RIGHT OF
 DECIMAL POINT
1010 INPUT W$
1020 IF POS(W$,".",1)=0 THEN 1040
1030 M1=M1 MAX LEN(W$)-POS(W$,".",1)
1040 REM
1050 RETURN
  ROUTINE TO CONSTRUCT TICK MARK LABEL WITH A GIVEN NUMBER
  PLACES, MI, TO THE RIGHT OF THE DECIMAL POINT
1060 W$=STR(ABS(I)*10 M1)
1070 W$=SEG(W$,2,LEN(W$)-1)
1080 IF M1=0 THEN 1170
1090
       IF M1 \le LEN(WS) THEN 1120
         U$=SEG("00000000000",1,M1-LEN(W$))
1100
1110
         WS=US&WS
1120
       REM
1130
       W=REP(".", LEN(W$)-M1+1,0)
1140
       IF ABS(I) = > 1 THEN 1160
         W\$ = REP("0", 1, 0)
1150
1160
       REM
1170 REM
1180 IF I=>0 THEN 1200
       WS = REP("-", 1, 0)
1190
1200 REM
1210 W$=W$&"#"
```

1220 RETURN

```
ROUTINE TO REPLACE BLANKS OR COMMAS WITH POUND SIGNS (#)
1230 FOR I=1 TO LEN(W$)
1240 U\$ = SEG(W\$, I, 1)
       IF U$<>" " AND U$<>"," THEN 1270
1250
         W$=REP("#",I,1)
1260
1270
       REM
1280 NEXT I
1290 W$=W$&"#"
1300 RETURN
              USER KEY 2: INPUT TITLES
1310 PAGE
1320 PRINT "X-AXIS LABEL:";
1330 INPUT X$
1340 PRINT "Y-AXIS LABEL:";
1350 INPUT Y$
1360 PRINT "PLOT TITLE:";
1370 INPUT Z$
1380 \text{ K(2)=1}
1390 PAGE
1400 RETURN
              USER KEY 4: INPUT AND OUTPUT OF DATA
1410 PAGE
1420 PRINT "INPUT (1) OR SAVE (2):";
1430 INPUT L
1440 PRINT "DATA TYPE (1=Y ONLY, 2=X&Y):";
1450 INPUT NO
              BRANCH ON WHETHER INPUT OR OUTPUT
1460 GO TO L OF 1470,2110
1470 REM
       PRINT "UNIT NUMBER (1=4907,2=4924,3=INTERNAL TAPE,4=KEYBOARD):";
1480
1490
       INPUT L
     PRINT "NUMBER OF CURVES:";
1500
1510
       INPUT N
       PRINT "MAXIMUM NUMBER OF POINTS PER CURVE:";
1520
1530
       INPUT MO
1540
       DELETE X,Y,M
       DIM X(N,M0),Y(N,M0),M(N)
1550
      X=0
1560
1570
     Y = 0
1580 FOR I=1 TO N
```

BRANCH ON DEVICE TYPE

```
GO TO 1*(L=1)+2*(L=2 \text{ OR } L=3)+3*(L=4) \text{ OF } 1600,1760,1920
1590
                        1.
                            INPUT FROM 4907 FILE MANAGER
1600
          REM
1610
            PRINT "FILE NAME FOR CURVE NUMBER "; I; ": ";
1620
            INPUT W$
1630
            OPEN W$;1,"R",U$
1640
            INPUT #1:M(I)
1650
            FOR J=1 TO M(I)
1660
              GO TO NO OF 1670,1700
1670
              REM
1680
                INPUT #1:Y(I,J)
1690
                GO TO 1720
1700
1710
                INPUT \#1:X(I,J),Y(I,J)
1720
              REM
1730
            NEXT J
1740
            CLOSE 1
1750
            GO TO 2070
                        2. INPUT FROM 4924 TAPE DRIVE OR INTERNAL DRIVE
                                    4924 ASSUMED AT ADDRESS 2 OF GPIB; SEE
                           LINE 9350)
1760
          REM
1770
            PRINT "FILE NUMBER FOR CURVE NUMBER "; I; ": ";
1780
            INPUT D1
1790
            D=D0*(L=2)+33*(L=3)
1800
            FIND @D:D1
1810
            INPUT @D:M(I)
1820
            FOR J=1 TO M(I)
1830
              GO TO NO OF 1840,1870
1840
1850
                INPUT @D:Y(I,J)
1860
                GO TO 1890
1870
1880
                INPUT @D:X(I,J),Y(I,J)
1890
              REM
1900
            NEXT J
1910
            GO TO 2070
                         3.
                             INPUT FROM KEYBOARD
1920
         REM
1930
            PAGE
1940
            PRINT "NUMBER OF POINTS IN CURVE NUMBER "; I; ": ";
1950
            INPUT M(I)
1960
            FOR J=1 TO M(I)
1970
              GO TO NO OF 1980,2020
1980
              REM
1990
                PRINT "Y(";I;",";J;"):";
2000
                INPUT Y(I,J)
```

57

```
2010
                GO TO 2050
2020
              REM
2030
                PRINT "X(";I;",";J;"),Y(";I;",";J;"):";
2040
                INPUT X(I,J),Y(I,J)
2050
              REM
2060
           NEXT J
2070
         REM
2080
       NEXT I
2090
       GOSUB 2650
2100
       GO TO 2630
2110 REM
2120
       IF K(4)=0 THEN 2570
2130
         PRINT "UNIT NUMBER (1=4907,2=4924,3=INTERNAL TAPE):";
2140
         INPUT L
2150
         FOR I=1 TO N
                   BRANCH ON DEVICE TYPE
2160
           GO TO 1*(L=1)+2*(L=2 \text{ OR } L=3) \text{ OF } 2170,2350
                       1. OUTPUT TO 4907 FILE MANAGER
2170
           REM
2180
              PRINT "FILE NAME FOR CURVE NUMBER "; I; ": ";
2190
              INPUT W$
2200
              KILL W$
              CREATE W$, "A"; 19+(19*(N0=1)+37*(N0=2))*M(I), 0
2210
              OPEN W$;1,"F",U$
2220
2230
              PRINT #1:M(I)
2240
              FOR J=1 TO M(I)
2250
                GO TO NO OF 2260,2290
2260
                REM
2270
                  PRINT #1:Y(I,J)
                  GO TO 2310
2280
2290
                REM
2300
                  PRINT \#1:X(I,J),Y(I,J)
2310
                REM
2320
              NEXT J
2330
              CLOSE 1
2340
              GO TO 2530
                        2. OUTPUT TO 4924 TAPE DRIVE OR INTERNAL DRIVE
                                    4924 ASSUMED AT ADDRESS 2 OF GPIB; SEE
                           (NOTE:
                           LINE 9350)
2350
            REM
2360
              PRINT "FILE NUMBER FOR CURVE NUMBER "; I; ": ";
2370
              INPUT D1
              D=D0*(L=2)+33*(L=3)
2380
2390
              KILL @D:D1
2400
              FIND @D:Dl
2410
              PRINT @D:M(I)
2420
              FOR J=1 TO M(I)
```

```
GO TO NO OF 2440,2470
2430
2440
               REM
                 PRINT @D:Y(I,J)
2450
                 GO TO 2490
2460
2470
               REM
                 PRINT @D:X(I,J),Y(I,J)
2480
2490
               REM
2500
             NEXT J
             PRINT @D, 2:
2510
2520
             CLOSE
2530
           REM
2540
         NEXT I
2550
         PAGE
2560
         GO TO 2620
              ERROR MESSAGE IF OUTPUT ATTEMPTED WITHOUT INPUT
2570
       REM
2580
         PAGE
         PRINT @32,21:35,50
2590
         PRINT "NO INPUT YET -- NOTHING TO SAVE"
2600
2610
         HOME
2620
       REM
2630 REM
2640 RETURN
              INPUT CURVE TYPES
2650 PAGE
2660 PRINT "CURVE TYPES AVAILABLE:"
2670 PRINT
2680 PRINT " 1.DASHED LINE"
2690 PRINT " 2.DASHED-DOTTED LINE"
2700 PRINT " 3.DOTTED LINE"
2710 PRINT " 4.SOLID LINE"
2720 PRINT " 5.CROSSES "
2730 PRINT " 6.X'S"
2740 PRINT " 7.SQUARES "
2750 PRINT " 8.TRIANGLES "
2760 PRINT " 9.FLASHES"
2770 PRINT
2780 DELETE L0,C0,A,B,R
2790 DIM LO(N), CO(N), A(N), B(N), R(N)
2800 A=0
2810 B=0
2820 C=0
2830 FOR I=1 TO N
       PRINT "TYPE FOR CURVE NUMBER "; I; ": ";
2840
       INPUT LO(I)
2850
2860 NEXT I
               INPUT LEGENDS
2870 PAGE
2880 F$=""
```

```
2890 FOR I=1 TO N
       PRINT "LEGEND FOR CURVE NUMBER "; I; ": ";
2900
2910
       INPUT W$
2920
       F$=F$&W$
       F$=F$&"#"
2930
2940 NEXT I
               INPUT COLORS
2950 PAGE
2960 FOR I=1 TO N
       PRINT "COLOR FOR CURVE NUMBER "; I; ": ";
2970
2980
       INPUT CO(I)
2990 NEXT I
               GENERATE X-AXIS DATA IF REQUESTED
3000 IF NO=2 THEN 3330
3010
       FOR I=1 TO N
3020
          FOR J=1 TO M(I)
3030
            X(I,J)=100*J/(1+M(I))
3040
         NEXT J
3050
       NEXT I
               SORT Y-AXIS DATA IF REQUESTED (USES BUBBLE SORT)
3060
       FOR I=1 TO N
3070
          IF M(I) \le 1 THEN 3310
            FOR J=2 TO M(I)
3080
3090
              IF Y(I,J-1) \le Y(I,J) THEN 3290
3100
                D1=Y(I,J)
3110
                L=J+1
3120
                D2=1
3130
                REM
3140
                  L=L-1
3150
                  IF L=1 THEN 3240
3160
                    IF Y(I,L-1)<=D1 THEN 3190
3170
                       Y(I,L)=Y(I,L-1)
3180
                       GO TO 3220
3190
                    REM
3200
                       Y(I,L)=D1
3210
                       D2 = 0
3220
                    REM
3230
                    GO TO 3270
3240
                  REM
3250
                    Y(I,1)=D1
3260
                    D2 = 0
3270
                  REM
3280
                IF D2 THEN 3130
3290
              REM
3300
           NEXT J
3310
         REM
3320
       NEXT I
3330 REM
```

```
3340 K(4)=1
3350 PAGE
3360 RETURN
```

3620 GOSUB 2650 3630 RETURN

USER KEY 9: GENERATE DATA FROM FUNCTIONS

```
3370 PAGE
3380 DIM R0(5)
3390 RESTORE 3400
3400 DATA 1,2,3,4,5
3410 READ R0
              DEFINE FUNCTIONS
3420 DEF FNX(T)=RO(I)*SIN(T)
3430 DEF FNY(T)=RO(I)*SIN(T)*COS(T)
3440 PRINT "DATA TYPE (1=Y ONLY, 2=X&Y):";
3450 INPUT NO
3460 PRINT "NUMBER OF CURVES:";
3470 INPUT N
3480 PRINT "NUMBER OF POINTS PER CURVE (AT LEAST 2):";
3490 INPUT MO
3500 DELETE X,Y,M
3510 DIM X(N,M0),Y(N,M0),M(N)
3520 M=M0
3530 PRINT "MIN AND MAX OF PARAMETRIC VARIABLE:";
3540 INPUT TO, T1
3550 S = (T1 - T0) / (M0 - 1)
              GENERATE DATA (NOTE: I INDEXES THE CURVES, J THE POINTS)
3560 FOR I=1 TO N
3570 FOR J=1 TO M0
       X(I,J)=FNX(T0+S*(J-1))
3580
        Y(I,J)=FNY(T0+S*(J-1))
3590
3600 NEXT J
3610 NEXT I
```

USER KEY 10: DRAW MENU

```
3640 D=32
3650 PAGE @D:
3660 DIM K$(80)
3670 K$=" LIMITS LABELS FORMAT IO FITS "
3680 K$=K$&" 4051 4662 S&R FUNCTION MENU '
3690 L=60
3700 D2=L
3710 FOR J=1 TO 2
3720 D1=-4
3730 FOR I=1 TO 5
```

```
3740
         D1 = D1 + 20
3750
         PRINT @D, 21: D1, D2
3760
         PRINT @D, 20:D1+16, D2, D1+16, D2-4, D1, D2-4, D1, D2
3770
       NEXT I
3780
       D2=D2-17.6
3790 NEXT J
3800 PRINT @D,21:23.8,L-8.4
3810 PRINT @D:"1"
3820 PRINT @D,21:43.8,L-8.4
3830 PRINT @D:"2"
3840 PRINT @D, 21:63.8, L-8.4
3850 PRINT @D:"3"
3860 PRINT @D,21:83.8,L-8.4
3870 PRINT @D:"4"
3880 PRINT @D,21:103.8,L-8.4
3890 PRINT @D:"5"
3900 PRINT @D,21:16,L-10.8
3910 PRINT @D,20:50,L-10.8
3920 PRINT @D,21:52,L-12
3930 PRINT @D:"USER DEFINABLE"
3940 PRINT @D,21:78,L-10.8
3950 PRINT @D,20:112,L-10.8
3960 PRINT @D,21:23.8,L-26
3970 PRINT @D:"6"
3980 PRINT @D,21:43.8,L-26
3990 PRINT @D:"7"
4000 PRINT @D, 21:63.8, L-26
4010 PRINT @D:"8"
4020 PRINT @D, 21:83.8, L-26
4030 PRINT @D:"9"
4040 PRINT @D, 21:102.5, L-26
4050 PRINT @D:"10"
4060 FOR J=1 TO 2
4070
       FOR I=1 TO 5
         PRINT @D, 21:17+20*(I-1), L-3.2-17.6*(J-1)
4080
         U\$=SEG(K\$,(J-1)*40+(I-1)*8+1,8)
4090
4100
         PRINT @D:U$
4110
       NEXT I
4120 NEXT J
4130 HOME @D:
4140 RETURN
               USER KEY 3: FORMAT DEFINITION
4150 PAGE
4160 PRINT "FRAME TYPE (0=NONE, 1=AXES, 2=GRID, 3=BORDER):";
4170 INPUT A0
4180 PRINT "COLOR FOR FRAME AND LABELS (1-8):";
4190 INPUT F0
4200 PRINT "PEN SPEED (10-570 MM/S):";
4210 INPUT S0
4220 PRINT
4230 PRINT "
                PAPER TYPES:
                                                         Y-AXIS"
                                             X-AXIS
```

```
4240 PRINT
4250 PRINT " 1.
                                                  Х
                     LINEAR:
                                                               Y"
4260 PRINT " 2.
                                             LOG(X)
                       XLOG:
                                                          LOG(Y)"
4270 PRINT " 3.
                       YLOG:
                                                  X
           4.
                                                          LOG(Y)"
4280 PRINT
                     LOGLOG:
                                             LOG(X)
                                                               ?"
4290 PRINT " 5.
                       USER:
4300 PRINT " 6.
                                                               Y"
                                              X/100
                    UNIFORM:
                                                               Y"
4310 PRINT " 7.
                                           N(X/100)
                     NORMAL:
                                                          LOG(Y)"
4320 PRINT " 8.
                                          N(X/100)
                 LOGNORMAL:
                                                               Y"
4330 PRINT " 9.
                   RAYLEIGH: SQR(-2*LOG(1-X/100))
                                                          LOG(Y)"
4340 PRINT "10.
                                LOG(-LOG(1-X/100))
                    WEIBULL:
4350 PRINT
4360 PRINT "PAPER TYPE:";
4370 INPUT P
4380 GOSUB 4410
4390 \text{ K}(3)=1
4400 RETURN
               BRANCH ON PAPER TYPE SELECTED FOR FUNCTION DEFINITION
4410 GO TO P OF 4420,4460,4500,4540,4580,4620,4660,4740,4820,4860
4420 REM
4430
       DEF FNA(X)=X
4440
       DEF FNB(Y)=Y
4450
       GO TO 4890
4460 REM
       DEF FNA(X) = LOG(X)
4470
       DEF FNB(Y)=Y
4480
4490
       GO TO 4890
4500 REM
4510
       DEF FNA(X)=X
4520
       DEF FNB(Y)=Log(Y)
       GO TO 4890
4530
4540 REM
4550
       DEF FNA(X) = LOG(X)
4560
       DEF FNB(Y)=LOG(Y)
       GO TO 4890
4570
4580 REM
4590
       DEF FNA(X)=X
       DEF FNB(Y)=Y
4600
4610
       GO TO 4890
4620 REM
4630
       DEF FNA(X)=X/100
       DEF FNB(Y)=Y
4640
4650
       GO TO 4890
4660 REM
       DEF FNA(X)=FNC((1-X/100)*(X>50)+X/100*(X<=50))*((X>50)-(X<=50))
```

DEF FNF(X)=1+(1.432788+(0.189269+0.001308*X)*X)*X

DEF FNC(X) = FND(X) - FNE(FND(X)) / FNF(FND(X))

DEF FNE(X)=2.515517+(0.802853+0.010328*X)*X

DEF FND(X)=SQR(LOG(1/(X*X)))

DEF FNB(Y)=YGO TO 4890

4670

4680 4690

4700 4710

4720

4730 4740 REM

```
DEF FNA(X) = FNC((1-X/100)*(X>50)+X/100*(X<=50))*((X>50)-(X<=50))
4750
4760
       DEF FNC(X) = FND(X) - FNE(FND(X)) / FNF(FND(X))
       DEF FND(X)=SQR(LOG(1/(X*X)))
4770
4780
       DEF FNE(X)=2.515517+(0.802853+0.010328*X)*X
       DEF FNF(X)=1+(1.432788+(0.189269+0.001308*X)*X)*X
4790
       DEF FNB(Y)=LOG(Y)
4800
       GO TO 4890
4810
4820 REM
       DEF FNA(X)=SOR(-2*LOG(1-X/100))
4830
       DEF FNB(Y)=Y
4840
4850
       GO TO 4890
4860 REM
       DEF FNA(X)=LOG(-LOG(1-X/100))
4870
       DEF FNB(Y) = LOG(Y)
4880
4890 REM
4900 PAGE
4910 RETURN
              USER KEY 8: STORE AND RETRIEVE PLOTS
4920 PAGE
4930 PRINT "STORE (1) OR RETRIEVE (2):";
4940 INPUT L
4950 PRINT "UNIT NUMBER (1=4907,2=4924,3=INTERNAL TAPE):";
4960 INPUT Dl
               BRANCH ON STORAGE OR RETRIEVAL
4970 GO TO L OF 4980,5310
4980 REM
       IF SUM(K) <> 5 THEN 5240
4990
                   BRANCH ON DEVICE TYPE
5000
         GO TO 1*(D1=1)+2*(D1=2 \text{ OR } D1=3) \text{ OF } 5010,5110
                       1. STORAGE ON 4907 FILE MANAGER
5010
         REM
           PRINT "FILE NAME:";
5020
           INPUT W$
5030
5040
           KILL W$
5050
           CREATE W$:845+8*(N1+N3+N*(2*M0+5)),0
           OPEN W$;1,"F",U$
5060
           WRITE #1:N1,N2,N3,N4,A$,B$,X$,Y$,Z$,N,M0,F$,A0,F0,S0,P,C
5070
5080
           WRITE #1:X1,Y1,X,Y,M,L0,C0,A,B
5090
           CLOSE 1
           GO TO 5210
5100
```

2. STORAGE ON 4924 TAPE DRIVE OR INTERNAL DRIVE (NOTE: 4924 ASSUMED AT ADDRESS 2 OF GPIB; SEE LINE 9350)

```
5110
         REM
           PRINT "FILE NUMBER:";
5120
5130
           INPUT D2
            D=D0*(D1=2)+33*(D1=3)
5140
           KILL @D:D2
5150
5160
            FIND @D:D2
            WRITE @D:N1,N2,N3,N4,A$,B$,X$,Y$,Z$,N,M0,F$,A0,F0,S0,P,C
5170
            WRITE @D:X1,Y1,X,Y,M,L0,C0,A,B
5180
            PRINT @D.2:
5190
            CLOSE
5200
5210
         REM
5220
         PAGE
         GO TO 5290
5230
               ERROR MESSAGE IF STORAGE ATTEMPTED BEFORE PLOT IS READY
5240
       REM
5250
         PAGE
         PRINT @32,21:30,50
5260
         PRINT "PLOT NOT COMPLETE -- NOT STOREABLE"
5270
5280
         HOME
5290
       REM
       GO TO 5540
5300
5310 REM
       DELETE X1, Y1, X, Y, M, L0, C0, A, B, R
5320
                   BRANCH ON DEVICE TYPE
       GO TO 1*(D1=1)+2*(D1=2 \text{ OR } D1=3) \text{ OF } 5340,5430
5330
                        1. RETRIEVAL FROM 4907 FILE MANAGER
5340
       REM
          PRINT "FILE NAME:";
5350
5360
          INPUT W$
          OPEN W$;1,"R",U$
5370
          READ #1:N1,N2,N3,N4,A$,B$,X$,Y$,Z$,N,M0,F$,A0,F0,S0,P,C
5380
          DIM X1(N1), Y1(N3), X(N, M0), Y(N, M0), M(N), LO(N), CO(N), A(N), B(N), R(
5390
          READ #1:X1,Y1,X,Y,M,L0,C0,A,B
5400
5410
          CLOSE 1
5420
          GO TO 5510
                        2. RETRIEVAL FROM 4924 TAPE DRIVE OR INTERNAL
                           DRIVE (NOTE: 4924 ASSUMED AT ADDRESS 2 OF
                           GPIB; SEE LINE 9350)
5430
        REM
          PRINT "FILE NUMBER:";
5440
          INPUT D2
5450
          D=D0*(D1=2)+33*(D1=3)
5460
```

```
5470
         FIND @D:D2
         READ @D:N1,N2,N3,N4,A$,B$,X$,Y$,Z$,N,M0,F$,A0,F0,S0,P,C
5480
         DIM X1(N1),Y1(N3),X(N,M0),Y(N,M0),M(N),L0(N),C0(N),A(N),B(N),R(N)
5490
         READ @D:X1,Y1,X,Y,M,L0,C0,A,B
5500
5510
       REM
5520
       GOSUB 4410
       K=1
5530
5540 REM
5550 RETURN
               USER KEY 5: CURVE FITS
5560 PAGE
5570 IF K(4)=0 THEN 6330
       PRINT "CURVE FITS (0=NO,1=YES):";
5580
5590
       INPUT C
       IF C=0 THEN 6280
5600
          IF K(3) THEN 5630
5610
            GOSUB 4150
5620
5630
          REM
          PRINT
5640
          PRINT "CURVE FITS AVAILABLE:"
5650
5660
          PRINT
          PRINT " 1.UNCONSTRAINED"
5670
          PRINT " 2.FIX SLOPE"
5680
          PRINT " 3.FIX INTERCEPT"
5690
          PRINT " 4.FIX BOTH"
5700
5710
          PRINT
          PRINT "CURVE FIT DESIRED:";
5720
5730
          INPUT C
               TRANSFORM DATA VIA FUNCTIONS DEFINING PAPER TYPE
5740
          FOR I=1 TO N
5750
            DELETE X0, Y0, Z0
            DIM XO(M(I)), YO(M(I)), ZO(M(I))
5760
            FOR J=1 TO M(I)
5770
              XO(J)=FNA(X(I,J))
5780
5790
              YO(J)=FNB(Y(I,J))
            NEXT J
5800
               BRANCH ON CURVE FIT SELECTED
            GO TO C OF 5820,5890,5940,6020
5810
5820
            REM
5830
              z_0 = x_0 * y_0
              A(I)=M(I)*SUM(ZO)-SUM(XO)*SUM(YO)
5840
              Z0=X0*X0
5850
              A(I)=A(I)/(M(I)*SUM(Z0)-SUM(X0)=2)
5860
              B(I) = (SUM(Y0) - A(I) *SUM(X0)) / M(I)
5870
              GO TO 6050
5880
5890
            REM
               PRINT "SLOPE OF CURVE NUMBER "; I; ": ";
5900
```

```
5910
              INPUT A(I)
              B(I) = (SUM(Y0) - A(I) *SUM(X0)) / M(I)
5920
              GO TO 6050
5930
5940
            REM
              PRINT "INTERCEPT OF CURVE NUMBER "; I; ": ";
5950
              INPUT B(I)
5960
              20 = x0 * y0
5970
              A(I)=SUM(ZO)-B(I)*SUM(XO)
5980
              z_0 = x_0 * x_0
5990
              A(I)=A(I)/SUM(ZO)
6000
6010
              GO TO 6050
6020
            REM
              PRINT "SLOPE, INTERCEPT OF CURVE NUMBER "; I; ": ";
6030
              INPUT A(I),B(I)
6040
6050
            REM
               CALCULATE R-SQUARE
            Z0=SUM(Y0)/M(I)
6060
            Z0 = Y0 - Z0
6070
            20 = 20 * 20
6080
            R(I)=1/SUM(ZO)
6090
            Z0=A(I)*X0
6100
            Z0=B(I)+Z0
6110
6120
            20 = Y0 - 20
            Z0 = Z0 \times Z0
6130
6140
            R(I)=100*(1-SUM(ZO)*R(I))
          NEXT I
6150
               PRINT OUT RESULTS OF CURVE FITS
6160
          PAGE
          FOR I=1 TO (34-(N+3))/2
6170
6180
            PRINT
6190
          NEXT I
                           CURVE #","
                                             SLOPE"," INTERCEPT"," R-SQUARE"
          PRI USI 6210:"
6200
6210
          IMAGE 8X,4(10A,5X)
6220
          PRINT
6230
          FOR I=1 TO N
            PRINT USING "8X,5X,2D,3X,3(5X,7D.2D)":I,A(I),B(I),R(I)
6240
6250
          NEXT I
6260
          HOME
          GO TO 6300
6270
6280
        REM
6290
          PAGE
6300
        REM
        K(5)=1
6310
6320
        GO TO 6370
               ERROR MESSAGE IF FIT ATTEMPTED BEFORE DATA INPUT
6330 REM
6340
        PRINT @32,21:25,50
        PRINT "NO DATA INPUT YET--CURVE FIT IMPOSSIBLE"
6350
```

```
6360
       HOME
6370 REM
6380 RETURN
              USER KEYS 6 AND 7: PLOT ON 4051 OR 4662
6390 PAGE @D:
              CHECK FOR MISSING PLOT PARAMETERS
6400 IF K(1) THEN 6420
     GOSUB 100
6410
6420 REM
6430 IF K(2) THEN 6450
6440
      GOSUB 1310
6450 REM
6460 IF K(3) THEN 6480
6470
      GOSUB 4150
6480 REM
6490 IF K(4) THEN 6510
6500
     GOSUB 1410
6510 REM
6520 IF K(5) THEN 6540
6530
       GOSUB 5560
6540 REM
              SELECT PEN COLOR AND SPEED
6550 PRINT @D,8:F0
6560 PRINT @D,32: "BY"; SO
              DEFINE WINDOW IN UDU'S
6570 U1=FNA(X1(1))
6580 U2=FNA(X1(N1))
6590 U3=FNB(Y1(1))
6600 U4=FNB(Y1(N3))
6610 WINDOW U1,U2,U3,U4
              DEFINE VIEWPORT IN GDU'S
                  D1 = HORIZONTAL LOCATION OF LOWER-LEFT CORNER
                  D2 = HORIZONTAL EXTENT
```

D3 = VERTICAL LOCATION OF LOWER-LEFT CORNER

D4 = VERTICAL EXTENT

6620 D1=26*(D<>32)+40*(D=32) 6630 D2=45*(D<>32)+60*(D=32) 6640 D3=15*(D<>32)+20*(D=32) 6650 D4=45*(D<>32)+60*(D=32) 6660 VIEWPORT D1,D1+D2,D3,D3+D4

CALCULATE SCALES AND TICK LENGTHS

```
6670 X2 = (U2 - U1)/D2
6680 \text{ Y2} = (\text{U4} - \text{U3})/\text{D4}
6690 X3=X2*(D2 MAX D4)/75
6700 Y3=Y2*(D2 MAX D4)/75
               DEFINE DEFAULT HARDWARE CHARACTER SIZES
6710 C1=1.792*(D<>32)+1.79*(D=32)
6720 C2=1.195*(D<>32)+1.195*(D=32)
6730 C3=2.816*(D<>32)+2.6*(D=32)
6740 C4=1.721*(D<>32)+2.2*(D=32)
               DEFINE RELATIVE CHARACTER SIZES FOR TICK MARK LABELS,
               AXIS LABELS, PLOT TILE, AND LEGENDS
6750 S1=0.8*(D<>32)+1*(D=32)
6760 S2=1*(D<>32)+1*(D=32)
6770 \text{ S3}=0.7*(D<>32)+1*(D=32)
               DEFINE OFFSETS FOR AXIS LABELS AND PLOT TITLE
6780 \text{ F1}=7*(D<>32)+10*(D=32)
6790 F2=10*(D<>32)+14*(D=32)
6800 F3=7*(D<>32)+9*(D=32)
               BRANCH ON FRAME TYPE (ZERO MEANS NO FRAME OR LABELS)
6810 IF A0=0 THEN 8060
6820 GO TO AO OF 6830,6990,7190
                    1. DRAW AXES
6830
      REM
6840
          MOVE @D:U1,U4
          FOR I=N3 TO 2 STEP -1
6850
            D2=FNB(Yl(I))
6860
            DRAW @D:U1,D2
6870
            DRAW @D:U1+X3,D2
6880
            DRAW @D:U1,D2
6890
6900
          NEXT I
          DRAW @D:U1,U3
6910
          FOR I=2 TO N1
6920
            D1=FNA(XI(I))
 6930
            DRAW @D:D1,U3
 6940
            DRAW @D:D1,U3+Y3
 6950
```

DRAW @D:D1,U3

NEXT I

GO TO 7570

6960

6970

6980

2. DRAW GRID

```
6990
       REM
7000
          MOVE @D:U1,U3
7010
         DRAW @D:U1,U4
7020
         D2=U4
7030
         FOR I=2 TO N1
7040
            D1=FNA(X1(I))
            DRAW @D:D1,D2
7050
            D2=U3*(D2=U4)+U4*(D2=U3)
7060
7070
            DRAW @D:D1,D2
7080
         NEXT I
          DRAW @D:U2,U3
7090
7100
          DRAW @D:U1,U3
7110
         D1=U1
7120
          FOR I=2 TO N3
            D2=FNB(Y1(I))
7130
            DRAW @D: D1, D2
7140
            D1=U1*(D1=U2)+U2*(D1=U1)
7150
7160
            DRAW @D:D1,D2
7170
          NEXT I
7180
          GO TO 7570

    DRAW BORDER

7190
       REM
7200
          MOVE @D:U1,U3
          IF N1=2 THEN 7280
7210
            FOR I=2 TO N1-1
7220
7230
              Dl=FNA(Xl(I))
7240
              DRAW @D:D1,U3
7250
              DRAW @D: D1, U3+Y3
7260
              DRAW @D:D1,U3
7270
            NEXT I
7280
          REM
7290
          DRAW @D:U2,U3
7300
          IF N3=2 THEN 7370
            FOR I=2 TO N3-1
7310
              D2=FNB(Y1(I))
7320
7330
              DRAW @D:U2,D2
              DRAW @D:U2-X3,D2
7340
7350
              DRAW @D:U2,D2
            NEXT I
7360
7370
          REM
7380
          DRAW @D:U2,U4
          IF N1=2 THEN 7460
7390
            FOR I=N1-1 TO 2 STEP -1
7400
              D1=FNA(X1(I))
7410
7420
              DRAW @D:D1,U4
              DRAW @D:D1,U4-Y3
7430
7440
              DRAW @D:D1,U4
7450
            NEXT I
7460
          REM
7470
          DRAW @D:U1,U4
```

```
7480
         IF N3=2 THEN 7550
7490
           FOR I=N3-1 TO 2 STEP -1
7500
              D2=FNB(Y1(I))
7510
              DRAW @D:U1,D2
7520
              DRAW @D:U1+X3,D2
7530
             DRAW @D:U1,D2
7540
           NEXT I
7550
         REM
7560
         DRAW @D:U1,U3
7570
       REM
              PRINT X-AXIS LABEL
7580
       PRINT @D,17:S1*C1,S1*C3
7590
       PRINT @D, 25:0
7600
       MOVE @D: (U1+U2-S1*X2*(C1*(LEN(X$)-1)+C2))/2,U3-F1*Y2
7610
       PRINT @D:X$
              PRINT Y-AXIS LABEL
7620
       IF D=32 THEN 7670
7630
         PRINT @D, 25:90
7640
         MOVE @D:U1-(F2-S1*C4)*X2,(U3+U4-S1*Y2*(C1*(LEN(Y$)-1)+C2))/2
7650
         PRINT @D:Y$
7660
         GO TO 7730
7670
7680
         FOR I=1 TO LEN(Y$)
7690
           MOVE U1-F2*X2, (U3+U4+Y2*S1*(C3*(LEN(Y$)-1)+C4))/2-Y2*(C4+C3*(I-1))
7700
           W$=SEG(Y$,I,1)
7710
           PRINT W$
7720
         NEXT I
7730
       REM
              PRINT AND UNDERLINE PLOT TITLE
7740
       IF LEN(Z$)=0 THEN 7830
7750
         PRINT @D,17:S2*C1,S2*C3
7760
         PRINT @D, 25:0
7770
         MOVE @D:(U1+U2-S2*X2*(C1*(LEN(Z$)-1)+C2))/2,U4+F3*Y2
         PRINT @D:Z$
7780
         MOVE @D,21:(U1+U2+S2*X2*(C1*(LEN(Z$)-1)+C2))/2,U4+(F3-0.2*S2*C3)*Y2
7790
7800
         MOVE @D,20:(U1+U2-S2*X2*(C1*(LEN(Z$)-1)+C2))/2,U4+(F3-0.2*S2*C3)*Y2
         MOVE @D,21:(U1+U2-S2*X2*(C1*(LEN(Z$)-1)+C2))/2,U4+(F3-0.4*S2*C3)*Y2
7810
7820
         MOVE 0,20:(U1+U2+S2*X2*(C1*(LEN(Z$)-1)+C2))/2,U4+(F3-0.4*S2*C3)*Y2
7830
       REM
7840
       PRINT @D, 17:S3*C1, S3*C3
7850
       PRINT @D, 25:0
              PRINT TICK MARK LABELS ON X AXIS
7860
       IF N2=0 THEN 7950
7870
         US = AS
7880
         FOR I=1 TO N2
7890
           W\$ = SEG(U\$, 1, POS(U\$, "#", 1) - 1)
```

```
7900
            U\$ = SEG(U\$, POS(U\$, "#", 1) + 1, LEN(U\$) - POS(U\$, "#", 1))
7910
            D1=FNA(VAL(W$))
7920
            MOVE \text{@D:D1-S3*X2*}(\text{C1*}(\text{LEN(W$)-1})+\text{C2})/2,\text{U3-S3*Y2*}(\text{1.25*C4})
7930
            PRINT @D:W$
7940
          NEXT I
7950
        REM
               PRINT TICK MARK LABELS ON Y AXIS
7960
        IF N4=0 THEN 8050
7970
          US=BS
7980
          FOR I=1 TO N4
7990
            W$=SEG(U$,1,POS(U$,"#",1)-1)
8000
            U$=SEG(U$, POS(U$, "#",1)+1, LEN(U$)-POS(U$, "#",1))
8010
            D1=FNB(VAL(W$))
            MOVE @D:U1-S3*X2*(C1*LEN(W$)-0.2*(C1-C2)),D1-S3*Y2*(1.125*C4)/2
8020
8030
            PRINT @D:W$
8040
          NEXT I
8050
        REM
8060 REM
8070 PRINT @D,17:S3*C1,S3*C3
8080 PRINT @D,25:0
8090 U$=F$
               LOOP OVER N DATA CURVES
8100 FOR I=1 TO N
               1. SELECT COLOR FOR I'TH CURVE
8110
       PRINT @D.8:C0(I)
               2. BRANCH ON CURVE TYPE
       GO TO 1*(LO(I) \le 3) + 2*(LO(I) = 4) + 3*(LO(I) = >5) OF 8130,8710,8810
8120
                    2.A DASHED LINES (CURVE TYPE 1 THROUGH 3)
8130
       REM
8140
          IF M(I)<=1 THEN 8690
                        2.A.1 LOAD IN DASHED LINE PARAMETERS (IN GDU'S)
                               (NOTE: 1'ST DASHED LINE HAS 3 ELEMENTS,
                               2'ND HAS 5,3'RD HAS 3)
8150
            RESTORE 8160
8160
            DATA 3,0.2,0.6,0.2,5,0.2,0.6,0.01,0.6,0.2,3,0.005,0.6,0.005
8170
            FOR J=1 TO LO(I)
8180
              READ L
8190
              DELETE PO
8200
              DIM PO(L)
8210
              READ PO
```

8220

NEXT J

2.A.2 TRANSFORM DATA

```
8230
            DELETE X0, Y0
8240
            DIM XO(M(I)), YO(M(I))
8250
            FOR J=1 TO M(I)
8260
              XO(J)=FNA(X(I,J))
8270
              YO(J)=FNB(Y(I,J))
8280
            NEXT J
                       2.A.3 CALCULATE CURVE LENGTH IN GDU'S
8290
            T0=0
8300
            FOR J=2 TO M(I)
8310
              T0=T0+SQR(((X0(J)-X0(J-1))/X2)=2+((Y0(J)-Y0(J-1))/Y2)=2)
8320
            NEXT J
                       2.A.4 CALCULATE ADJUSTED DASHED LINE PARAMETERS
8330
           Ml=1 MAX INT(T0/SUM(P0)+0.5)
8340
            P0=T0/(M1*SUM(P0))*P0
                       2.A.5 MOVE TO START OF CURVE
8350
            J=1
8360
            D1=X0(J)
8370
            D2=Y0(J)
8380
            MOVE @D:D1,D2
                       2.A.6 LOOP OVER M1 PATTERNS AND L ELEMENTS IN
                              EACH PATTERN
8390
            FOR Il=1 TO M1
8400
              FOR J1=1 TO L
8410
                D3 = 0
8420
                D4 = 0
8430
                REM
                       2.A.7 CALCULATE DISTANCE TO NEXT DATA POINT;
                              IF GREATER THAN PATTERN ELEMENT, INTER-
                              POLATE TO FIND WHERE TO GO AND SET FLAG
                              TO INDICATE DONE WITH ELEMENT -- IF LESS,
                              GO TO NEXT DATA POINT
8440
                  D5 = (X0(J+1)-D1)/X2
8450
                  D6 = (Y0(J+1)-D2)/Y2
8460
                  D7 = SQR(D5 = 2 + D6 = 2)
8470
                  IF D4+D7=>P0(J1) THEN 8530
8480
                    J=J+1
8490
                    D1=X0(J)
8500
                    D2=YO(J)
8510
                    D4 = D4 + D7
8520
                    GO TO 8590
8530
                  REM
8540
                    IF D7<=1.0E-4 THEN 8570
```

```
8550
                      D1=D1+X2*(P0(J1)-D4)*D5/D7
8560
                      D2=D2+Y2*(P0(J1)-D4)*D6/D7
8570
                    REM
8580
                    D3 = 1
8590
                  REM
                       2.A.8 IF EVEN-NUMBERED ELEMENT BEING PROCESSED,
                              MOVE; IF ODD-NUMBERED, DRAW
8600
                  IF J1=2*INT(J1/2) THEN 8630
8610
                    DRAW @D: D1, D2
8620
                    GO TO 8650
8630
                  REM
8640
                    MOVE @D:D1,D2
8650
                  REM
                       2.A.9 TEST IF DONE WITH CURRENT ELEMENT
8660
                IF D3<>1 THEN 8430
8670
              NEXT J1
8680
           NEXT Il
8690
         REM
8700
         GO TO 9180
                   2.B SOLID LINE (CURVE TYPE 4)
8710
       REM
8720
         D1=FNA(X(I,1))
8730
         D2=FNB(Y(I,1))
8740
         MOVE @D:D1,D2
8750
         FOR J=1 TO M(I)
           Dl = FNA(X(I,J))
8760
8770
           D2=FNB(Y(I,J))
8780
           DRAW @D: D1, D2
8790
         NEXT J
8800
         GO TO 9180
                   2.C SYMBOLS (CURVE TYPES 5 THROUGH 9)
8810
       REM
8820
         FOR J=1 TO M(I)
8830
           Dl = FNA(X(I,J))
8840
           D2=FNB(Y(I,J))
           GO TO LO(I)-4 OF 8860,8920,8980,9050,9110
8850
                       2.C.1 CROSSES
8860
           REM
8870
              MOVE @D:D1+1.5*X3,D2
              DRAW @D:D1-1.5*X3,D2
8880
              MOVE @D:D1,D2-1.5*Y3
8890
8900
             DRAW @D:D1,D2+1.5*Y3
8910
             GO TO 9160
```

2.C.2 X-SHAPED

```
8920
           REM
              MOVE @D:D1+X3,D2+Y3
8930
              DRAW @D: D1-X3, D2-Y3
8940
8950
              MOVE @D:D1-X3,D2+Y3
              DRAW @D: D1+X3, D2-Y3
8960
8970
              GO TO 9160
                       2.C.3 SOUARES
8980
           REM
8990
              MOVE @D:D1-X3,D2-Y3
9000
              DRAW @D:D1-X3,D2+Y3
              DRAW @D:D1+X3,D2+Y3
9010
              DRAW @D: D1+X3, D2-Y3
9020
9030
              DRAW @D: D1-X3, D2-Y3
              GO TO 9160
9040
                        2.C.4 TRIANGLES
9050
           REM
              MOVE @D:D1,D2+2*Y3/SQR(3)
9060
9070
              DRAW @D:D1+X3,D2-Y3/SOR(3)
9080
              DRAW @D: D1-X3, D2-Y3/SQR(3)
              DRAW @D:D1,D2+2*Y3/SQR(3)
9090
              GO TO 9160
9100
                        2.C.5 UPSIDE-DOWN TRIANGLES
9110
           REM
              MOVE @D:D1,D2-2*Y3/SQR(3)
9120
              DRAW @D: D1-X3, D2+Y3/SQR(3)
9130
              DRAW @D: D1+x3, D2+y3/sQR(3)
9140
              DRAW @D:D1,D2-2*Y3/SQR(3)
9150
9160
           REM
9170
         NEXT J
9180
       REM
                   3. PRINT LEGEND FOR I'TH CURVE
       W$=SEG(U$,1,POS(U$,"#",1)-1)
9190
       U\$ = SEG(U\$, POS(U\$, "#", 1) + 1, LEN(U\$) - POS(U\$, "#", 1))
9200
9210
       D1=FNA(X(I,M(I)))
9220
       D2=FNB(Y(I,M(I)))
       MOVE @D:D1+3*X3,D2-0.5*S3*Y2*(1.125*C4)
9230
9240
       PRINT @D:W$
                   4. PLOT CURVE FIT IF REQUIRED
9250
       IF C=0 THEN 9280
          MOVE @D:U1, A(I) *U1+B(I)
9260
9270
          DRAW @D:U2,A(I)*U2+B(I)
```

9280 REM 9290 NEXT I

RETURN PEN TO HOLDER AND EXIT

9300 PRINT @D,8:0

9310 HOME @D: 9320 RETURN

INITIALIZATION ROUTINE

ARRAY K IS USED TO KEEP TRACK OF WHICH USER KEYS HAVE BEEN DEPRESSED; LINE 9350 DEFINES THE ADDRESS OF THE 4924 TAPE DRIVE

9330 DIM K(5),R\$(1)

9340 R\$=REP("",1,0)

9350 D0=2

9360 IF LEN(R\$)>0 THEN 9390

9370 K=0

9380 R\$=" "

9390 REM

9400 RETURN

DISTRIBUTION LIST TR-368

No. of Copies	Organization	No. of Copies	Organization
3	Commander US Army Materiel Development and Readiness Command ATTN: DRCDM-S DRCDE-SD DRCDE-SA 5001 Eisenhower Avenue Alexandria, VA 22333	5	Commander US Army Armament Research and Development Command ATTN: DRDAR-SE DRDAR-LCS DRDAR-SCF DRDAR-SCS DRCPM-ADG Dover, NJ 07801
2	Commander Defense Technical Information Center ATTN: TCA Cameron Station Alexandria, VA 22314	2	Commander US Army Aviation Research and Development Command ATTN: DRDAV-B DRDAV-E PO Box 209
2	Chief Defense Logistics Studies Information Exchange US Army Logistics Management Center ATTN: DRXMC-D FT Lee, VA 23801	1	St. Louis, MO 63166 Commander US Army Electronics Research and Development Command ATTN: DRDEL-ST-SA (A. Sambuco) 2800 Powder Mill Road
1	HQDA (SAUS-OR) WASH DC 20310	1	Adelphi, MD 20783 Commander US Army Troop Support and
1	HQDA (DAMO-RQA) WASH DC 20310		Aviation Materiel Readiness Command ATTN: DRSTS-BA
2	Commander US Army Concepts Analysis Agency		4300 Goodfellow Boulevard St. Louis, MO 63120
	ATTN: CSCA-MR CSCA-ADL 8120 Woodmont Avenue Bethesda, MD 20014	2	Commander US Army Combat Developments Experimentation Command ATTN: ATEC-PL-M ATEC-PL-TL
1	Commander US Army Operational Test and Evaluation Agency ATTN: CSTE-STS-L 5600 Columbia Pike Falls Church, VA 22041	2	Director US Army TRADOC Systems Analysis Activity ATTN: ATAA-PL ATAA-TG
			White Sands Missile Range, NM 88002

DISTRIBUTION LIST (Continued) TR-368

No. of Copies	Organization	No. of Copies	Organization
1	Commandant US Army Air Defense School ATTN: ATSA-CD-A FT Bliss, TX 79916	1	AFELM, The Rand Corporation ATTN: Library-D 1700 Main Street Santa Monica, CA 90406
1	Commander US Army Aviation Center and Fort Rucker ATTN: ATZQ-CD FT Rucker, AL 36362	1	Tektronix, Inc. Information Display Division Applications Library Group 451 P.O. Box 500 Beaverton, Oregon 97077
1	President US Army Air Defense Board ATTN: ATZC FT Bliss, TX 79916	3	Aberdeen Proving Ground Cdr, USATECOM ATTN: DRSTE-CT
2	Commander US Army White Sands Missile Range ATTN: STEWS-TE-ML	1	DRSTE-AD DRSTE-CM Dir, HEL ATTN: DRXHE-SP
	STEWS-NR-PA White Sands Missile Range, NM 88002	2	Dir, BRL ATTN: DRDAR-BLB
1	Commander US Army Tank-Automotive Com ATTN: DRDTA-V	nmand	DRDAR-TSB-S (STINFO)
	Warren, MI 48090		
1	Commander US Army Missile Command ATTN: DRSMI-DS Redstone Arsenal, AL 35809)	
1	Commander US Army Armament Materiel Readiness Command ATTN: DRSAR-IEP-L Rock Island, IL 62199		

DISTRIBUTION LIST (Continued) TR-368

Number of Copies

Organization

46

```
Dir, AMSAA
       DRXSY-A (D. O'Neill)
ATTN:
       DRXSY-AD (H. Peaker)
       DRXSY-AA (T. Coyle)
       DRXSY-ADG (J. Meredith)
       DRXSY-ADG (D. Drake)
       DRXSY-ADG (J. Foulkes)
       DRXSY-ADG (K. Frounfelker)
       DRXSY-ADG (B. Lufkin 5 cys)
       DRXSY-ADG (R. Sebra)
       DRXSY-ADG (J. Wald)
       DRXSY-AAM (J. Passamonte)
       DRXSY-AAM (P. Hill)
       DRXSY-AAM (J. Hennessey)
       DRXSY-AA (T. Coyle)
       DRXSY-GI
       DRXSY-GS
       DRXSY-GA
       DRXSY-GB
       DRXSY-GP
       DRXSY-CC
       DRXSY-CS
       DRXSY-CM
       DRXSY-CR
       DRXSY-CI
       DRXSY-CA
       DRXSY-RW
       DRXSY-RE
       DRXSY-RV
       DRXSY-RM
       DRXSY-FA
       DRXSY-FX
       DRXSY-FM
       DRXSY-FR
       DRXSY-FO
       DRXSY-FLSO
       DRXSY-FIRO
       DRXSY-P
       DRXSY-J
       DRXSY-DA
       DRXSY-PRO
       DRXSY-HEL
       DRXSY-A (Editorial Ofc)
```